



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 7462B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	TO REPAIR SEE LABOUR	2,883.00	-
1	FRONT BONNET RUBBER	NOT NECESSARY	162.00	-
1	FRONT HEADLAMP (RH)	HOLDER CRACKED	3,617.00	3,617.00
1	FRONT HEADLAMP PANELS	TO REPAIR SEE LABOUR	218.00	-
1	FRONT BUMPER	DISTORTED	1,887.00	1,789.00
1	FRONT BUMPER INNER FRAME	NOT NECESSARY	199.00	-
1	FRONT BUMPER LOWER CHROME MOULDING	NOT NECESSARY	185.00	-
1	FRONT BUMPER SIDE GRILLE	NOT NECESSARY	142.00	-
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	155.00	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	182.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	522.00	-
2	FRONT BUMPER REINFORCEMENT STAY BRACKET @ \$277.00	NOT NECESSARY	554.00	-
2	FRONT BUMPER SIDE RETAINERS @\$75.50	O/S CRACKED	151.00	75.50
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	50.00	-
6	FRONT BUMPER PDC SENSORS @\$358.00	SHORTED (1 PCS ONLY)	2,148.00	305.00
1	FRONT FENDER (RH)	DENTED	1,085.00	1,012.00
1	FRONT FENDER INNER SHIELD (RH)	SERVICEABLE	185.00	-
	LESS 10% DISCOUNT		-1,432.50	-679.85
			12,892.50	6,118.65
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	60.00	-
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	65.00	50.00
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	55.00	-
1	FRONT ALLOY RIM (RH) (SN)	CUT	800.00	500.00
1	FRONT TYRE (RH) (SN)	SERVICEABLE	500.00	-
			1,480.00	550.00

Report Ref No. CS/FCI22009464/Uny3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT HEADLAMP PANELS .		1,000.00	400.00
	SPRAY PAINTING.		800.00	600.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.		80.00	20.00
	TO REMOVE & REFIT FRONT SENSOR .		100.00	50.00
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR .		200.00	80.00
	TO APPLY UNDERCOATING FOR RUST PROOFING.		100.00	30.00
			2,280.00	1,180.00
	GRAND TOTAL		16,652.50	7,848.65
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,200.00

Report Ref No. CS/FCI22009464/Uny3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.