

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | | |
|------------------------------------|---|--------------------------|----------------|-------|-------------------------|--|
| | AXA INSURANCE I | PTE LTD | | Ref: | CS3/ASM22003461/Rvy3e2 | |
| | 8 SHENTON WAY SINGAPORE 0688 | #24-01 AXA TOWER 11 | | Date: | 06/05/2022 | |
| | ATTN: KOH JANIC | E | | Code: | ASM | |
| 1. | 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | SLP 449M | Veh. Inspected | k | SNC 7770H | |
| | Policy No. | GA469061/1 | Coverage (\$) | | 0.00 | |
| | Claim No. | S2M03YIX | Excess (\$) | | 0.00 | |
| | Assign From | KOH JANICE | Assign Date | | 14/04/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | TOYOTA COROLLA ALTIS ELE | c.c | | 1598 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2021 | |
| | Chassis No. | MR2BE3BE900016307 | Colour | | GREY | |
| | Odometer | 6358 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | FAIR | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 225/45 R17 | DUNLOP | | 6 mm | |
| | L/H Front Tyre | 225/45 R17 | DUNLOP | | 6 mm | |
| | R/H Rear Tyre | 225/45 R17 | DUNLOP | | 6 mm | |
| | L/H Rear Tyre | 225/45 R17 | DUNLOP | | 6 mm | |
| 4. | . Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 12/04/2022 | Inspect Date / | Time | 18/04/2022 (12:28 PM) | |
| | Survey held at SIN HUP LEE SERVICE CO | | | | | |
| | BLK 1005 BUKIT MERAH LANE 2 #01-20 SINGAPORE 159761 | | | | | |
| 5a. | Remarks | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000 | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days | | | | | |

Report Ref No. CS3/ASM22003461/Rvy3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

PEOP Auto Occupion OAF Licensed Association

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$