

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 3766T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED / TORN	595.00	595.00
1	N/S REAR BUMPER REFLECTOR	BROKEN	60.00	60.00
1	N/S REAR BUMPER BRACKET	NOT NECESSARY	87.50	-
10	REAR BUMPER CLIPS @ \$4.50	NECESSARY	45.00	45.00
1	N/S REAR BUMPER SIDE RETAINER	BENT	95.00	95.00
1	N/S REAR BUMPER SIDE HOLDER	NOT NECESSARY	55.00	-
1	N/S REAR LAMP LED	NOT NECESSARY	364.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	485.00	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	285.00	-
	LESS 25% DISCOUNT		-517.88	-198.75
			1,553.62	596.25
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER PARKING SENSOR (SN)	NOT NECESSARY	350.00	-
			350.00	-
	<u>LABOUR</u>			
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	60.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		680.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		550.00	400.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		80.00	40.00
			1,430.00	760.00
	GRAND TOTAL		3,333.62	1,356.25

Report Ref No. CS/AGI22009470/Uqy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,050.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI22009470/Uqy3m4

CHUA KANG SENG
Licensed Appraiser