



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 2835D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (N) (CONSISTENT)	TO REPAIR SEE LABOUR	1,578.00	-
1	FRONT BUMPER OUTER GARNISH (N) (CONSISTENT)	CUT	135.00	135.00
1	FRONT BUMPER SIDE RETAINER RH (N) (CONSISTENT)	SERVICEABLE	55.00	-
1	FRONT BUMPER SENSOR RH (N) (CONSISTENT)	SCRATCHED	215.00	215.00
1	HEADLAMP RH (N) (CONSISTENT)	SERVICEABLE	3,480.00	-
1	FRONT WHEEL ARCH PANEL RH (N) (CONSISTENT)	CUT	250.00	250.00
	LESS 10% DISCOUNT		-571.30	-60.00
			5,141.70	540.00
LABOUR				
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PANEL BEAT FRONT BUMPER ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		650.00	250.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS .		800.00	250.00
	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS.	NOT NECESSARY	150.00	-
			1,680.00	520.00
GRAND TOTAL			6,821.70	1,060.00
RECOMMENDED COST OF REPAIRS				1,060.00

Report Ref No. CC4/ASM22009472/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.