



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 8208B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LOGO EMBLEM	NECESSARY	41.00	41.00
1	MIVEC EMBLEM	NECESSARY	26.00	26.00
1	ATTRAGE EMBLEM	NECESSARY	20.00	20.00
1	REAR BUMPER	DEFORMED	896.00	751.00
1	REAR BUMPER LOWER SPOILER	CRACKED	468.00	468.00
6	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER RETAINERS	NOT NECESSARY	44.00	-
1	END PANEL	TO REPAIR SEE LABOUR	602.00	-
1	LH TAILLAMP	NOT NECESSARY	296.00	-
	LESS 10% DISCOUNT		-242.30	-133.60
			2,180.70	1,202.40
<u>SPECIAL NETT ITEMS</u>				
1	CC EMBLEM (SN)	NECESSARY	20.00	20.00
1	REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
			270.00	220.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF END PANEL .		600.00	300.00
	SPRAY PAINTING.		600.00	600.00
	WIRING.		30.00	30.00
	RUST PROOFING.		80.00	30.00
			1,310.00	960.00
GRAND TOTAL			3,760.70	2,382.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CS/AGI22009473/Avy3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.