

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122009474/ANY3Q2**Date:** 14/06/2023REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG22011789
Claimant Vehicle No :	PC8305M	Insured Vehicle No :	YQ7596R
Date of Loss:	24/09/2022	Nature of Claim:	TP
		Claim No:	CDMCG22002004

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC8305M	Engine No:	1GD8428921
Make & Model:	TOYOTA HIACE, 2.8 D COMMUTER GL (A)	Chassis No:	GDH2232001917
Reg. Date:	28/06/2019 (Man. Year: 2019)	Odometer:	240939 km
Colour:	Silver		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,438.95	1,857.45	2,581.50	58.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	660.00	1,340.00	67.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,438.95	2,517.45	3,921.50	60.90
Approved Total (Overridden) (S\$)		2,000.00		
Nett Amount (S\$)	6,438.95	2,000.00	4,438.95	68.94

INSPECTION

Date of Assignment:	26/09/2022	Unimotor Company - Kaki Bukit (HQ) 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) Singapore 417883
Date Inspected:	04/10/2022 Inspected At:	
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2023)
Parts:	213	TOYOTA HIACE 2.8 D COMMUTER GL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC8305M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT L/H DOOR WIND MIRROR ASSY	Damaged	1,225.40 FL	*1,225.40 FL
2	1		*FRONT L/H FENDER WIND MIRROR ASSY	Cut	632.20 FL	*632.20 FL
3	1		*FRONT BUMPER FACE	Cut	855.20 FL	*589.00 FL
4	1		*FRONT BUMPER L/H FOG LAMP COVER	Not Necessary	86.00 FL	*- FL
5	1		*FRONT BUMPER L/H SIDE RETAINER	Not Necessary	139.60 FL	*- FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	55.00 FL	*30.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	441.60 FL	*- FL
8	1		*FRONT L/H HEADLAMP ASSY	Not Necessary	1,850.50 FL	*- FL
9	1		*FRONT L/H STEP PANEL ASSY	Not Necessary	362.30 FL	*- FL
10	1		*FRONT L/H STEP PANEL GARNISH	Not Necessary	155.60 FL	*- FL
11	1		*FRONT L/H CABLE SOCKET HOLDER	Not Necessary	115.20 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	5,918.60 2,476.60
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,479.65 619.15
					Total Parts (S\$)	4,438.95 1,857.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM/REWIRE DAMAGED SOCKET HOLDER HEADLAMP	New	180.00	30.00
2	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	900.00	400.00
3	TO PUTTY AND RESPRAY DAMAGED DOOR STEP PANEL DOOR PILLAR	New	800.00	200.00
4	TO SPRAY UNDERCOATING IN REPAIR	New	120.00	30.00
Gross Labour Cost (S\$)			2,000.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >