

Vehicle Damage Assessment Report for [PC8305M]

Estimate Created: 13/06/2023 15:15 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 13/06/2023 15:21 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number	CDMCG22002004
Claim Type	TP		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Toyota	Model	Hiace
Engine Type			
License Plate Number	PC8305M	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$2,000.00 WITH 3 WORKING DAYS	Insurlogic 4 (13/06/2023 15:21)
--	---------------------------------

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
LH front door wind mirror assy		1	1225.40	-25.00 %	919.05
LH front fender wind mirror assy		1	632.20	-25.00 %	474.15
Front bumper face		1	589.00	-25.00 %	441.75
Front bumper clips		1	30.00	-25.00 %	22.50

Parts Subtotal 1,857.45

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
To dismantle/rewire damage socket holder headlamp	RnR	30.00	0.00 %	30.00
Panel beating	RnR	400.00	0.00 %	400.00
To spray undercoating in repair.	RnR	30.00	0.00 %	30.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	200.00	0.00 %	200.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 460.00

Paint Labor Subtotal 200.00

Labor Subtotal 660.00

Summary

Repair Cost 2,517.45

Discount(20 %) (503.49)

2,013.96

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 2,013.96