



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 1531C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER (CONSISTENT)	TORN	695.20	695.20
1	FRONT BUMPER SIDE HOLDER RH (CONSISTENT)	NOT NECESSARY	38.40	-
1	FRONT RH FENDER (CONSISTENT)	DISTORTED	598.40	598.40
1	FRONT RH FENDER INNER SHIELD (CONSISTENT)	DEFORMED	189.50	189.50
1	FRONT RH FENDER GLASS GARNISH (CONSISTENT)	NOT NECESSARY	68.20	-
1	HEADLAMP RH (CONSISTENT)	CRACKED	989.40	989.40
1	FRONT RH DOOR (CONSISTENT)	DENTED	1,154.20	1,154.20
1	FRONT RH DOOR WEATHERSTRIPE(CONSISTENT)	NOT NECESSARY	214.90	-
1	FRONT RH LOWER ARM (CONSISTENT)	BENT	391.40	391.40
1	FRONT RH SHOCK ABSORBER (CONSISTENT)	BENT	349.50	349.50
1	FRONT RH KNUCKLE ARM (CONSISTENT)	DAMAGED	448.40	448.40
1	FRONT RH WHEEL HUB C/W BEARING (CONSISTENT)	DAMAGED	299.20	299.20
1	FRONT RH ANTI ROLL BAR LINKAGE (CONSISTENT)	NOT NECESSARY	114.90	-
	LESS 20% DISCOUNT		-	-1,023.04
			5,551.60	4,092.16
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT RH FENDER INNER SHIELD CLIPS (SN)(CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT RH FENDER GLASS SEALANT (SN)(CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT RH DOOR BLACK TAPE (SN)(CONSISTENT)	NECESSARY	60.00	60.00
1	FRONT RH WHEEL RIM (SN)(CONSISTENT)	CUT	850.00	480.00
1	FRONT RH TYRE (SN)(CONSISTENT)	NOT NECESSARY	280.00	-
			1,290.00	640.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		1,000.00	700.00
	SPRAY PAINTING.		1,000.00	600.00
	WIRING .		50.00	30.00
	TO APPLY TUFF COAT.		150.00	60.00
	TO TRANSFER FRONT DOOR FITTINGS.		150.00	80.00

Report Ref No. CC4/ASM22009476/Apa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE FRONT UNDERCARRIAGE.		350.00	220.00
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
			2,850.00	1,770.00
GRAND TOTAL			9,691.60	6,502.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00

Report Ref No. CC4/ASM22009476/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.