

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 8061A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	620.20	-
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	62.40	-
1	REAR FENDER	TO REPAIR SEE LABOUR	1,255.30	-
1	REAR DOOR	TO REPAIR SEE LABOUR	1,355.50	-
1	SIDE SKIRT	TO REPAIR SEE LABOUR	708.00	-
	LESS 25% DISCOUNT		-1,000.35	-
			3,001.05	-
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET SIDE SKIRT CLIPS (SN)	NOT NECESSARY	15.00	-
1	WHEEL RIM (SN)	CUT	1,200.00	480.00
1	WHEEL TYRE (SN)	NOT NECESSARY	380.00	-
			1,615.00	500.00
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVING AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR FENDER ,REAR DOOR AND SIDE SKIRT .		1,200.00	200.00
	SPRAY PAINTING TO AFFECTED AREA .		1,200.00	600.00
	TUFF COAT.		180.00	30.00
	WIRING CHECK .		150.00	30.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	NOT NECESSARY	80.00	-
	FOUR WHEEL ALIGNMENT.		100.00	80.00
			2,910.00	940.00
	GRAND TOTAL		7,526.05	1,440.00

Report Ref No. CS/INC22009484/Any3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED) 1,440.00

Report Ref No. CS/INC22009484/Any3e2

XXX.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.