

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22009487/KPA3Q2**Date:** 12/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210116802
Claimant Vehicle No :	SHB7678T	Insured Vehicle No :	SNC3169X
Date of Loss:	17/09/2022	Nature of Claim:	TP
		Claim No:	3970032636SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7678T		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2C02869
Reg. Date:	22/03/2019 (Man. Year: 2018)	Chassis No:	JTDKB3FU003079506
Colour:	Metallic Pearl White/Red	Odometer:	312845 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,176.35	771.75	3,404.60	81.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,290.00	370.00	9,920.00	96.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,466.35	1,141.75	13,324.60	92.11
Approved Total (Overridden) (\$\$)		900.00		
Nett Amount (\$\$)	14,466.35	900.00	13,566.35	93.78
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	26/09/2022		
Date Inspected:	26/09/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	1.5 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Repair	442.60 FL	*- FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*COVER ,REAR BUMPER ,LOWER	Serviceable	15.40 FL	*- FL
4	1		*GUARD ,REAR BUMPER CENTER	Dented / Cut	576.30 FL	*576.30 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
6	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	117.70 FL	*- FL
7	1		*BOARD ASSY ,BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
8	1		*WEATHERSTRIP BACK DOOR	Serviceable	372.30 FL	*- FL
9	1		*BOARD ,BACK DOOR TRIM	Serviceable	225.20 FL	*- FL
10	1		*COVER ,FLOOR UNDER NO.1 LH	Serviceable	175.10 FL	*- FL
11	1		*COVER ,FLOOR UNDER NO.2 RH	Serviceable	241.90 FL	*- FL
12	1		*COVER ,REAR FLOOR CTR	Serviceable	229.90 FL	*- FL
13	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
14	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
15	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
16	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*60.00 FS
17	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*30.00 FS
18	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
19	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	140.00 FS	*- FS
20	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,146.80	999.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	970.45	227.25
Total Parts (\$\$)	4,176.35	771.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	-
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,200.00	150.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT ,VACUUM AND CHARGE-IN -GAS	New	380.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
12	TOWING FEES	New	150.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	220.00
14	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
16	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
17	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
18	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
19	TO LIFT-UP/OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
20	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS -MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
21	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (\$\$)			10,290.00	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >