



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 2021C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT FENDER LH	TO REPAIR SEE LABOUR	735.00	-
1	FRT DOOR LH	TO REPAIR SEE LABOUR	1,894.00	-
	LESS 10% DISCOUNT		-262.90	-
			2,366.10	-
	<u>SPECIAL NETT ITEMS</u>			
1	FRT SPORT RIM (SN)	CUT	580.00	580.00
			580.00	580.00
	<u>LABOUR</u>			
	TO REMOVE ,TRANSFER FRT DOOR COMPONENTS .	NOT NECESSARY	100.00	-
	TO REMOVE ,REPAIR & REPLACE DAMAGED BODYPARTS ,REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF FRT FENDER LH AND FRT DOOR LH .		400.00	400.00
	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS.		500.00	400.00
	RUST PROOFING ON AFFECTED PORTIONS.		80.00	20.00
			1,080.00	820.00
GRAND TOTAL			4,026.10	1,400.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CS/SMO22009489/Kny3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.