



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|---|---|------------|
| AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: OH VALE | | | Ref: CS/ASM22009495/Awy3m4 Date: 22/12/2022 Code: ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SMF 8696D | Veh. Inspected | SKS 4083D |
| | Policy No. | VPA/P2219806 | Coverage (\$) | 0.00 |
| | Claim No. | S2M04B3Z | Excess (\$) | 0.00 |
| | Assign From | OH VALE | Assign Date | 27/09/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | VOLKSWAGEN JETTA | c.c | 1390 |
| | Engine No. | HIDDEN | Year of Reg. | 2015 |
| | Chassis No. | WVWZZZ16ZEM066257 | Colour | BRONZE |
| | Odometer | 125122 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 225/45 R17 | GOODYEAR | 6 mm |
| | L/H Front Tyre | 225/45 R17 | GOODYEAR | 6 mm |
| | R/H Rear Tyre | 225/45 R17 | GOODYEAR | 6 mm |
| | L/H Rear Tyre | 225/45 R17 | GOODYEAR | 6 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY & UNDERCARRIAGE. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 14/09/2022 | Inspection Date | 27/09/2022 |
| | Survey held at | YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 9 Working Days | |