

SKS4083D.

TP AX4.

Volkswagen Jetta.

Xin Yu.

WVWZZZ16ZEM066257

Reer Bumper	Deformed	1198	✓
Reer Bumper Clips.	✓	30(SN)	✓
Reer Bumper Side Holder RH.	NP ✓	55	+
Reer RH Fender	Distorted	1205	✓
Reer RH Fender Inner Panel	Ryis	798.	+
Reer RH Fender Inner Shield	NP ✓	195	+
Reer Windscreen Moulding.	✓	188	✓
Reer Windscreen Sealant.	✓	60(SN)	✓
Reer RH Door	Distorted	1295	✓
Reer RH Door Lock	Damaged	325	✓
Reer RH Door Weatherstripe	✓	298	✓
Reer RH Door Outer Handle.	NP ✓	121	+
Reer RH Door Inner Trim Board	NP ✓	656	+
Reer RH Door Inner Trim Board Clips	NP ✓	30(SN)	+

SKS4083D.

Rear RH Door Glass	Regulator Gear	Dryd	278.	✓
Rear RH Door Glass	Regulator Motor	HT m	314.	X
Rear RH Door Glass	Chisel Rubber.	m	142.	✓
Rear Panel	RH.	Regis	852.	X
Rear RH Wheel Rim.		ut	800(SN) 600(SN)	
Rear RH Tyre		XHP m	350(SN)	X
Rear RH Lower Arm.			430	✓
Rear RH Shock Absorber		Bent	345	✓
Rear RH Knuckle Arm.		Dryd	689	✓
Rear RH Wheel Hub c/w Bearings.		Dryd	323	✓
Rear RH Trailing Arm.		Bent	273.	✓
Rear RH Upper Arm.			259.	✓
Rear Sub Frame.		Bent	1128.	✓

837b

7538.40

SN: 690

SKS 4083D

Panel Beating	1600 800.
Spry Painting.	1400 800.
Wiring.	50 30.
To spry tuff coat	150 60
To remove upholstery.	150 60
To remove reverse sensor	100 50
To remove rear windsreen.	180 120
To transfer rear door fittings.	150 80
To remove rear undercarriage.	380 300.
To perform wheel alignment (King Roller)	120 ✓

Total: 10648.40

H/S: 8.5K
09 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: