

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III22009498/UPA3Q2**Date:** 27/06/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000461_01

Claimant Vehicle No : JPL8239 **Insured Vehicle No :** XE1348E

Date of Loss: 26/09/2022 Nature of Claim: TP Claim No: MFL2022D0005501

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JPL8239**
 Make & Model: TOYOTA INNOVA, 2.0 G (A) Engine No: 1TR7553335
 Reg. Date: 04/07/2013 (Man. Year: 2013) Chassis No: PN111NV4008636109
 Colour: Silver Odometer: 297066 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/65 R15 Rear Tyre Size: 205/65 R15
 Front Left Side: Dunlop 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,356.10	5,395.07	10,961.03	67.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	1,990.00	1,430.00	41.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,776.10	7,385.07	12,391.03	62.66
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	19,776.10	5,500.00	14,276.10	72.19
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 27/09/2022

Date Inspected: 28/09/2022 Inspected At: Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki
 Bukit
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2023)
Parts:	M1-MPV	TOYOTA INNOVA 2.0 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JPL8239)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER O/S	Repair	845.10 F	*- FL
2	1		*FRONT FENDER INNER SHIELD O/S	Not Necessary	299.20 F	*- FL
3	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Not Necessary	50.00 F	*- FL
4	1		*FRONT SPORT RIM O/S	Cut	1,200.00 FS	*450.00 FS
5	1		*FRONT SHOCK ABSORBER O/S	Not Necessary	485.20 F	*- FL
6	1		*FRONT KNUCKLE ARM O/S	Not Necessary	655.20 F	*- FL
7	1		*FRONT DOOR O/S	Badly Dented	1,645.10 F	*1,645.10 FL
8	1		*FRONT DOOR OUTER HANDLE O/S	Not Necessary	182.40 F	*- FL
9	1		*FRONT DOOR GLASS REGULATOR & MOTOR O/S	Not Necessary	847.90 F	*- FL
10	2		*FRONT DOOR HINGES	Not Necessary	210.00 F	*- FL
11	1		*REAR BUMPER INNER RUBBER O/S	Not Necessary	151.00 F	*- FL
12	1		*FRONT DOOR INNER LOCK O/S	Not Necessary	683.20 F	*- FL
13	1		*FRONT DOOR INNER TRIM BOARD O/S	Not Necessary	980.20 F	*- FL
14	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	Not Necessary	50.00 F	*- FL
15	1		*SET FRONT DOOR FRAME BLACK STICKER O/S	Necessary	115.00 F	*80.00 FL
16	1		*FRONT DOOR OUTER PROTECTOR O/S	Cut / Necessary	288.90 F	*288.90 FL
17	1		*FRONT DOOR INNER RUBBER O/S	Necessary	366.50 F	*290.00 FL
18	1		*FRONT DOOR MIRROR ASSY O/S	Cracked	1,105.20 F	*850.00 FL
19	1		*FRONT DOOR MIRROR COVER O/S	Cracked	145.00 F	*145.00 FL
20	1		*FRONT DOOR MIRROR SIGNAL LAMP O/S	Not Necessary	85.00 F	*- FL
21	1		*REAR DOOR O/S	Dented / Bent	1,866.20 F	*1,566.00 FL
22	1		*REAR DOOR INNER RUBBER O/S	Necessary	322.20 F	*290.00 FL
23	1		*SET REAR DOOR FRAME BLACK STICKER O/S	Necessary	180.00 F	*80.00 FL
24	1		*REAR DOOR OUTER PROTECTOR O/S	Cut / Necessary	380.00 F	*280.00 FL
25	1		*REAR FENDER O/S	Cracked / Dented	945.10 F	*945.10 FL
26	1		*REAR BUMPER	Repair	922.50 F	*- FL
27	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 F	*- FL
28	1		*REAR SPORT RIM O/S	Repair	1,200.00 F	*- FL
29	1		*REAR FENDEER GLASS SEALANT O/S	Necessary	40.00 FS	*40.00 FS
30	1		*SET BOTH DOOR VISOR O/S	Necessary	60.00 FS	*60.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					16,356.10	7,010.10
- List Item Discount on L Items 0.00/25.00% (\$\$)					0.00	1,615.03
Total Parts (\$\$)					16,356.10	5,395.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	0.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
4	TO DISMANTLE & REFIX FRONT UNDER CARRIAGE	New	150.00	0.00
5	TO DISMANTLE & REFIX FRONT DOOR MECHANISM	New	100.00	60.00
6	TO DISMANTLE & REFIX REAR DOOR MECHANISM	New	100.00	60.00
7	TO SPRAY RUST PROOFING	New	120.00	90.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,200.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	900.00
Gross Labour Cost (\$\$)			3,420.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >