



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22009499/Uvy3m4	
			Date: 21/10/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2510X	Veh. Inspected	JPU 4120	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D20001079MFSH	Excess (\$)	0.00	
Assign From	AINI BINTE	Assign Date	27/09/2022	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA 135LC	c.c	135	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	PMYUG0410D0204342	Colour	BLACK	
Odometer	37434 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/90-17	IRC	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90-17	IRC	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION & N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/02/2020	Inspection Date	29/09/2022	
Survey held at	BISADO TECHNOLOGIES LLP 1 KAKI BUKIT AVENUE 6, #02-32, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	