

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22009501/ECY3E2**Date:** 11/10/2022**REFERENCE**

Insured/Claimant: BOON BEN BERNARD TAN Policy No: SP2002564379-01
Date of Loss: 26/09/2022 Nature of Claim: OD Claim No: 202222007043JK

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF3844M**
Make & Model: MAZDA BIANTE, 2.0 SKYACTIV-G SP.6EAT (A) Engine No: PE30927227
Reg. Date: 24/08/2016 (Man. Year: 2016) Chassis No: JM6CC1071G0110183
Colour: White Odometer: 127984 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$74,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Firenza 4 mm Rear Left Side: Firenza 4 mm
Front Right Side: Firenza 4 mm Rear Right Side: Firenza 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,004.30	5,914.30	90.00	1.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	1,450.00	10.00	0.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,464.30	7,364.30	100.00	1.34
- Excess (S\$)	0.00	300.00	-300.00	
(S\$)	7,464.30	7,064.30	400.00	5.36
+ GST 7.00/7.00% (S\$)	522.50	494.50	28.00	5.36
Nett Amount (S\$)	7,986.80	7,558.80	428.00	5.36

INSPECTION

Date of Assignment: 27/09/2022
Date Inspected: 27/09/2022 Inspected At: Mova Automotive Pte Ltd
15 Fan Yong Road
Singapore 629792
Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2022)

Parts: M1-MPV MAZDA BIANTE 2.0 SKYACTIV-G SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLF3844M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE (WCP)	Broken	1,350.00 F	*1,350.00 F
2	1		*FRONT GRILLE TOP MOUNTING LH (CHROME) (WCP)	Broken	290.00 F	*290.00 F
3	1		*FRONT GRILLE LOWER MOUNTING LH (CHROME) (WCP)	Broken	320.00 F	*320.00 F
4	1		*FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
5	1		*FRONT BUMPER (WCP)	Broken	680.00 F	*680.00 F
6	1		*FRONT BUMPER SIDE RETAINER BRACKET LH (WCP)	Broken	48.00 F	*48.00 F
7	1		*FRONT BUMPER UPPER BOLDER BRACKET LH (WCP)	Broken	65.00 F	*65.00 F
8	1		*FRONT BUMPER FOG LAMP FINISHER COVER LH (WCP)	Cut	110.00 F	*110.00 F
9	1		*FRONT BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
10	1		*FRONT NUMBER PLATE	Not Necessary	30.00 FS	*- FS
11	1		*FRONT NUMBER PLATE HOLDER	Not Necessary	20.00 FS	*- FS
12	1		*FRONT SUPPORT PANEL (WCP)	Broken	360.00 F	*360.00 F
13	1		*FRONT HEADLAMP LH (WCP)	Broken	1,350.00 F	*1,350.00 F
14	1		*FRONT FENDER LH (WCP)	Dented	260.00 F	*260.00 F
15	1		*FRONT FENDER INNER LINER LH (WCP)	Torn	110.00 F	*110.00 F
16	1		*FRONT FENDER LINER CLIPS LH	Necessary	40.00 FS	*20.00 FS
17	1		*FRONT FENDER UPPER LAMP LH (WCP)	Cut	370.00 F	*370.00 F
18	1		*FRONT BONNET (REPAIR) (NPA)	Repair	-	*- F
19	1		*FRONT WHEEL HOUSE LH (REPAIR) (NPA)	Repair	-	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,473.00	5,383.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	531.30	531.30
Total Parts (\$\$)	6,004.30	5,914.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING & ELECTRICAL SYSTEM	New	60.00	50.00
2	TO REMOVE, REPLACE, REPAIR & READJUST FRONT ACCIDENT AREAS SUCH AS FRONT BONNET, FRONT BUMPER, FRONT SUPPORT PANEL, FRONT WHEEL HOUSE LH & FRONT FENDER LH. BACK TO ORIGINAL CONDITIONS	New	600.00	600.00
3	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT WHEEL HOUSE LH & FRONT FENDER LH	New	800.00	800.00
Gross Labour Cost (\$)			1,460.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >