



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 9960P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (CONSISTENT) (SN)	NOT NECESSARY	3,200.00	-
1	REAR BUMPER FRAME (CONSISTENT) (SN)	NOT NECESSARY	1,500.00	-
1	REAR CORNER BUMPER LH (CONSISTENT) (SN)	CRACKED	1,280.00	750.00
1	REAR CORNER BUMPER LAMP LH (CONSISTENT) (SN)	CRACKED	280.00	180.00
1	REAR CORNER BUMPER STICKER LH (CONSISTENT) (SN)	NECESSARY	100.00	50.00
1	TAILLAMP LH (CONSISTENT) (SN)	NOT NECESSARY	780.00	-
			7,140.00	980.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		800.00	250.00
	SPRAY PAINTING.		600.00	250.00
	WIRING.		100.00	30.00
	TO SPRAY TUFF COAT.		100.00	30.00
			1,600.00	560.00
<b>GRAND TOTAL</b>			<b>8,740.00</b>	<b>1,540.00</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,200.00</b>
---	--	--	-----------------

Report Ref No. CS/ASM22009502/Avy3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.