



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 9699J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HEADLAMP ASSY - LH (CONSISTENT)	BROKEN	7,733.90	7,733.90
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,196.90	1,196.90
1	FRONT BUMPER RETAINER - LH (CONSISTENT)	CUT	133.20	133.20
10	FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	80.00	80.00
1	FRONT BUMPER COVER - LH (CONSISTENT)	CUT	85.40	85.40
1	FRONT BUMPER LOWER SKIRT - LH (CONSISTENT)	CUT	142.60	142.60
1	FRONT BUMPER LIP - CENTER (CONSISTENT)	CRACKED	170.70	170.70
1	FRONT FOG LAMP - LH (CONSISTENT)	CRACKED	303.80	303.80
1	FOG LAMP GARNISH - LH (CONSISTENT)	CUT	79.90	79.90
1	FRONT FOG LAMP MOULDING CHROME - LH (CONSISTENT)	CUT	89.90	89.90
1	FRONT FENDER - LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,498.90	-
1	FRONT FENDER ARCH - LH (CONSISTENT)	CUT	239.60	239.60
10	FRONT FENDER ARCH CLIP - LH (CONSISTENT)	NECESSARY	60.00	60.00
1	FRONT BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	3,131.90	-
1	AIR GUIDE - LH (ADDITIONAL) (CONSISTENT)	CRACKED	123.80	45.00
1	CORNERING LAMP - LH (ADDITIONAL) (CONSISTENT)	BROKEN	1,174.20	435.00
1	FRONT SENSOR - LH (ADDITIONAL) (CONSISTENT)	CUT	480.90	280.00
1	HEADLAMP NOZZLE - LH (ADDITIONAL) (CONSISTENT)	BROKEN	914.90	274.00
1	FOG LAMP BRACKET - LH (ADDITIONAL) (CONSISTENT)	BROKEN	169.90	55.00
1	FRONT BUMPER SPONGE (ADDITIONAL) (CONSISTENT)	CRACKED	118.90	118.90
	LESS 10% DISCOUNT		-1,792.93	-1,152.38
			16,136.37	10,371.42
<u>LABOUR</u>				
	TO DIAGNOSE AND CALIBRATE FRONT SENSOR WIRING SYSTEM, SAFETY SYSTEMS, PARKING AID SENSORS & RE-SET OF SAME.		600.00	80.00
	TO DIAGNOSE RE-CALIBRATE ADAPTIVE FRONT LIGHTING SYSTEM, (LEXUS TRIPLE-BEAM LED HEADLIGHTS), WITH A SUITE SENSORS & RE-SET OF SAME.	NOT NECESSARY	550.00	-

Report Ref No. CS/ASM22009504/Gvy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SET WHEEL ALIGNMENT & RESET OF SAME.	NOT NECESSARY	200.00	-
	TO DISMANTLE DAMAGED PARTS; TO HEAT / WELD, CUT-OFF THE FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT CHASSIS FRAME LH, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST OF SAME. INCLUSIVE OF THE REPAIR OF FRONT FENDER - LH AND FRONT BONNET.		850.00	400.00
	TO PUTTY AND SPRAY PAINT (PREMIUM) ON AFFECTED AREAS.		1,800.00	750.00
	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS.		150.00	60.00
			4,150.00	1,290.00
GRAND TOTAL			20,286.37	11,661.42
RECOMMENDED COST OF REPAIRS				11,661.42

Report Ref No. CS/ASM22009504/Gvy3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.