AB ENGINEERING PTE LTD

Co. Reg No: 202117273R

10 KAKI BUKIT ROAD 2 #01-25, FIRST EAST CENTRE, SINGAPORE 417868

Tel: 8858 6282

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SMZ9699J Report No: SA1X229Q0001

Chassis No: JTJBZMCA802011436

Engine No: SNB2574X : 27/9/2022 Date

MAKE: TOYOTA

MODEL: LEXUS RX350 LUXURY AT SR TYPE : COMMERCIAL

Replacement of Damaged Parts

S/No.	Description	Qty	Our Recommendation
	Parts Items		
1	Headlamp assy - LH / BK	1	7733.90
2	Front bumper / CC	1	1196.90
3	Front bumper retainer - LH / Cut	1	133.20
4	Front bumper clip / MCC	10	80.00
5	Front bumper cover - LH / WT ,	1	85.40
6	Front bumper lower skirt - LH / Cut ,	1	142.60
7	Front bumper lip - Center ?	1	170.70
8	Front fog lamp - LH ?	1	303.80
9	Fog lamp garnish - LH / /	1	79.90
10	Front fog lamp moulding chrome - LH / 7 W	1	89.90
11	Front fender - LH X Ruphi	1	1498.90
12	Front fender arch - LH / Af .	1	239.60
13	Front fender arch clip - LH	10	60.00
14	Front bonnet X Almir -	1	3131.90
	7-7		\$14,946.70
		Less 10%	\$1 494 67

Less 10% \$1,494.67 \$13,452.03 **Total Parts:**

Labour Charges

To diagnose and calibrate front sensor wiring system, safety systems, parking aid sensors & re-set of same.

\$600.00

To diagnose re-calibrate adaptive front lighting system (Lexus

triple-beam led headliaghts), with a suite sensors & re-set of same.

\$550.00

To re-set wheel alignment & re-set of same.

\$200.00 × NN

To dismantle damaged parts; to heat/weld, cut-off the front bonnet, front bumper, front fender LH, front chassis frame LH, including replacement of parts and align where necessary, to refit and adjust of same.

\$850.00 (600

To putty and spray paint (premium) on affected areas.

\$1,800.00 750

* To appy rust-proofing on replaced and repaired panels.

\$150.00 60

Total Labour:	 \$4,150.00

Final Repair Cost to Vehicle No: SMZ9699J

Amount	\$17,602.03
Lump Sum Discount -20%	\$ 3,520.41
Total	 \$14,081.62
Add GST 7%	\$ 985.71
Grand Total	\$15,067.34

4 Days.

pad by pat.

hefar protot phos.

Gra Qiang - 82880282

27/9/22.

LKK Auto Consu the Repairer of t • To resurvey before	he following:		
To display damage			
Parts print the		100	
Third :		· · · · · · · · dice * basis	
• No illa			
• Supr		and.	
is sub	al trom	pany	
Acknc '	rer		
Signa!			
Date			