

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDZ 7711B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	CRACKED	5,800.00	4,200.00
2	FRONT BUMPER BRACKET @\$850.00 (CONSISTENT)	DISTORTED (1PC ONLY)	1,700.00	280.00
2	FRONT BUMPER STOPPER @\$328.00 (CONSISTENT)	DENTED / CUT	656.00	656.00
2	HEADLAMP @\$1800.00 (CONSISTENT)	SERVICEABLE	3,600.00	-
2	HEADLAMP GARNISH @\$389.00 (CONSISTENT)	SERVICEABLE	778.00	-
1	FRONT BUMPER LOWER PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	2,800.00	-
2	FRONT BUMPER FOG LAMP @\$480.00 (CONSISTENT)	SERVICEABLE	960.00	-
2	FRONT SIGNAL LAMP @\$298.00 (CONSISTENT)	SERVICEABLE	596.00	-
1	FRONT NOSE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	2,688.00	-
	LESS 10% DISCOUNT		-1,957.80	-513.60
			17,620.20	4,622.40
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE (SN) (CONSISTENT)	DENTED	150.00	45.00
			150.00	45.00
	<u>LABOUR</u>			
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER PANEL AND FRONT NOSE PANEL.		1,800.00	500.00
	TO PUTTY AND SPRAY PAINTING.		1,800.00	800.00
	TO RESEAL AND ANTI-RUST.	NOT NECESSARY	450.00	-
	TO CHECK, REPLACE, REPAIR WIRING AND RESET FAULT CODE.		800.00	30.00
	BREAKE SEAL & RESEAL NO. PLATE.		80.00	80.00
			4,930.00	1,410.00
	GRAND TOTAL		22,700.20	6,077.40

Report Ref No. CS/ASM22009508/Kny3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,800.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/ASM22009508/Kny3e2

KONG SENG CHEONG

Licensed Appraiser