



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 2646Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SIDE GATE RH (CONSISTENT)	DENTED	1,846.00	1,846.00
1	SIDE GATE SAFETY LOCK RH (CONSISTENT)	NOT NECESSARY	132.10	-
6	SIDE GATE HINGE RH @\$95.90 (CONSISTENT)	DENTED (1 PCS ONLY)	575.40	95.90
1	REAR WHEEL BACK MUDGUARD RH (CONSISTENT)	DENTED	185.00	185.00
1	REAR WHEEL BACK MUDFLAG RH (CONSISTENT)	NOT NECESSARY	115.00	-
1	CARGO BED SIDE END PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,428.00	-
1	REAR EXHAUST PIPE BRACKET (CONSISTENT)	NOT NECESSARY	78.90	-
	LESS 25% DISCOUNT		-1,090.10	-531.73
			3,270.30	1,595.17
<u>SPECIAL NETT ITEMS</u>				
1	SIDE GATE SEALANT RH (SN) (CONSISTENT)	NECESSARY	150.00	60.00
1	SIDE GATE INNER COVER (ALUMINIUM) RH (SN) (CONSISTENT)	NOT NECESSARY	680.00	-
1	SIDE GATE COMPANY STICKER (SN) (CONSISTENT)	NECESSARY	450.00	300.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	250.00	-
1	REAR TOOLS BOX RH (SN) (CONSISTENT)	DISTORTED	500.00	350.00
			2,030.00	710.00
<u>LABOUR</u>				
	TO PANEL BEAT WELD CUT ,ADJUST ,KNOCK .INCLUSIVE OF THE REPAIR OF CARGO BED SIDE END PANEL RH .		1,400.00	400.00
	TO PUTTY ,SPRAY PAINT,POLISH WAX.		1,000.00	500.00
	REMOVE AND REFIX REAR RAILING.		350.00	80.00
	REMOVE AND REFIX CARGO BED COVER ALUMINIUM .	NOT NECESSARY	650.00	-
	REMOVE AND REFIX CANOPY.		350.00	150.00
	REMOVE AND REFIX SIDE GATE ALUMINIUM.		200.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			4,130.00	1,160.00
GRAND TOTAL			9,430.30	3,465.17
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CC4/ASM22009511/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.