

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009519/UNY3M4**Date:** 10/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00098972201		
Claimant Vehicle No :	SDF3232Z	Insured Vehicle No :	ER91H		
Date of Loss:	23/09/2022	Nature of Claim:	TP	Claim No:	SNM22D206845/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDF3232Z	Engine No:	27682430155675
Make & Model:	MERCEDES-BENZ S400L, 3.0 R19 LED (A)	Chassis No:	WDD2221652A143772
Reg. Date:	19/05/2015 (Man. Year: 2014)	Odometer:	121519 km
Colour:	Black		
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R19	Rear Tyre Size:	275/40R19
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,044.80	9,642.82	1,401.98	12.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,440.00	920.00	1,520.00	62.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,484.80	10,562.82	2,921.98	21.67
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	13,484.80	9,500.00	3,984.80	29.55
+ GST 7.00/7.00% (S\$)	943.94	665.00	278.94	29.55
Nett Amount (S\$)	14,428.74	10,165.00	4,263.74	29.55

INSPECTION

Date of Assignment:	27/09/2022		
Date Inspected:	03/10/2022	Inspected At:	Precise Auto Service (HQ) No 1 Kaki Bukit Ave 6, #02-34/36 Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Note* NEW PARTS REPLACEMENT

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2023)
Parts:	143	MERCEDES-BENZ S400L 3.0 R19 LED (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDF3232Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Deformed/Torn	1,942.50 FL	*1,916.00 FL
2	1		*BUMPER SIDE RETAINER (N/S)	Cracked	58.00 FL	*58.00 FL
3	1		*BUMPER L/H OUTER FRAME	Twisted	330.00 FL	*266.00 FL
4	1		*BUMPER L/H INNER FRAME	Twisted	460.00 FL	*245.00 FL
5	1		*BUMPER SPONGE	Torn	268.25 FL	*182.00 FL
6	1		*BUMPER PDC SENSOR INNER - L/H	Shorted	814.00 FL	*265.00 FL
7	1		*BUMPER PDC SENSOR OUTER - L/H	Shorted	370.00 FL	*265.00 FL
8	6		*BUMPER PDC O-RINGS	Necessary	402.00 FL	*180.00 FL
9	1		*BUMPER REINFORCEMENT	Bent	800.00 FL	*800.00 FL
10	1		*BUMPER L/H GRILLE	Twisted	157.25 FL	*157.25 FL
11	1		*BUMPER L/H GRILLE MOULDING	Cracked	130.00 FL	*130.00 FL
12	1		*BUMPER L/H GRILLE COVER	Twisted	130.00 FL	*130.00 FL
13	1		*BUMPER CENTRE GRILLE	Twisted	110.00 FL	*110.00 FL
14	1		*HEADLAMP L/H	Broken	5,200.00 FL	*5,200.00 FL
15	1		*FRONT GRILLE	Cracked	810.00 FL	*810.00 FL
16	1		*HEADLAMP HID BULB	Not Necessary	290.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	12,272.00	10,714.25
- List Item Discount on L Items 10.00/10.00% (S\$)	1,227.20	1,071.43
Total Parts (S\$)	11,044.80	9,642.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	80.00	20.00
2	TO RESET HEADLAMP MODULE SYSTEM	New	480.00	100.00
3	TO REPLACE DAMAGED PARTS, STRAIGHTEN AND REPAIR FENDER AND ALIGN ALL PARTS	New	850.00	400.00
4	TO RESPRAY AFFECTED AREAS	New	850.00	400.00
5	TO TUFF-COAT AFFECTED AREAS	New	180.00	0.00
Gross Labour Cost (\$\$)			2,440.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >