



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2022)
<b>Parts:</b> 143	LEXUS IS 250 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SMY8634H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (50%)	Deformed	906.39 FS	*500.00 FS
2	1		*REAR BUMPER INNER SPONGE	Cracked	128.00 FL	*128.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	475.70 FL	*- FL
4	2		*REAR BUMPER REVERSE SENSOR	Damaged	983.00 FL	*600.00 FL
5	2		*REAR BUMPER REVERSE SENSOR COVER	Necessary	113.00 FL	*50.00 FL
6	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	107.40 FL	*- FL
7	1		*REAR END PANEL	Not Necessary	869.30 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
9	1		*SET REAR END PANEL TRIM COVER CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>3,672.79</b>	<b>1,308.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	267.64	77.80
<b>Total Parts (S\$)</b>	<b>3,405.15</b>	<b>1,230.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	250.00	0.00
2	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	40.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	80.00	0.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS,REPAIR PORTION ,AND WHERE CONSISTENT T TO THE ACCIDENT	New	500.00	200.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT T TO THE ACCIDENT	New	600.00	200.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	40.00	0.00
			<b>Gross Labour Cost (S\$)</b>	<b>1,530.00</b>
				<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >