

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009522/ENY3Q2**Date:** 30/11/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00015382100

**Claimant Vehicle No :** SKL2666Y **Insured Vehicle No :** SMG6294M

Date of Loss: 16/09/2022 Nature of Claim: TP Claim No: SNM22D206871/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL2666Y**

Make & Model: ALFA ROMEO GIULIA SUPER, 2.0 (A) Engine No: 1101986

Reg. Date: 25/10/2018 (Man. Year: 2018) Chassis No: ZAREAEKN6J7587442

Colour: Grey Odometer: 70785 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/50 R17 Rear Tyre Size: 215/50 R17

Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm

Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,138.10	3,294.07	844.03	20.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,800.00	2,200.00	3,600.00	62.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,938.10</b>	<b>5,494.07</b>	<b>4,444.03</b>	<b>44.72</b>
<b>+ GST 7.00/7.00% (S\$)</b>	695.67	384.58	311.09	44.72
<b>Nett Amount (S\$)</b>	<b>10,633.77</b>	<b>5,878.65</b>	<b>4,755.12</b>	<b>44.72</b>

INSPECTION

Date of Assignment: 27/09/2022

Date Inspected: 28/09/2022 Inspected At: 24 Leng Kee Road #08-01  
Repairer: EuroAutomobile Pte Ltd (HQ)

Estimated Period of Repair: 3.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 30 Nov 2022)**Parts:** 143      ALFA ROMEO GIULIA SUPER 2.0 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKL2666Y)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,706.09 FL	*1,706.09 FL
2	1		*REAR DIFFUSER	Cut	1,718.69 FL	*1,718.69 FL
3	2		*REAR BUMPER CLIPS		5.82 FL	*- FL
4	1		*REAR BUMPER BRACKET LHS	Not Necessary	100.47 FL	*- FL
5	1		*REAR BUMPER BRACKET RHS	Not Necessary	96.97 FL	*- FL
6	1		*REAR BUMPER REAR CENTRE BRACKET	Not Necessary	180.25 FL	*- FL
7	4		*REAR BUMPER SENSORS	Not Necessary	417.76 FL	*- FL
8	4		*REAR BUMPER SENSORS RING		46.80 FL	*- FL
9	1		*REAR BUMPER SENSORS WIRE	Not Necessary	206.97 FL	*- FL
10	1		*REAR CROSSRAIL	Broken	692.81 FL	*692.81 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,172.63</b>	<b>4,117.59</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,034.53	823.52
<b>Total Parts (\$\$)</b>	<b>4,138.10</b>	<b>3,294.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REPLACE REAR BUMPER	New	1,000.00	850.00
2	LABOUR TO REMOVE & REPLACE REAR DIFFUSER	New	1,000.00	0.00
3	LABOUR TO SPRAY FRONT BUMPER	New	1,000.00	850.00
4	TO REMOVE & REPLACE REAR PARKING SENSOR	New	1,000.00	0.00
5	TO REMOVE & REPLACE REAR PARKING SENSORS WIRE	New	1,000.00	0.00
6	TO CONDUCT PRE/POST DIAGNOSTIC CHECK	New	800.00	500.00
			<b>Gross Labour Cost (\$)</b>	<b>2,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >