

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009525/KNY3Q2**Date:** 19/12/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00023482203
<b>Claimant Vehicle No :</b>	GBL9475S	<b>Insured Vehicle No :</b>	YJ5355U
Date of Loss:	23/09/2022	Nature of Claim:	TP
		Claim No:	SNM22D206820/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBL9475S</b>		
Make & Model:	MERCEDES-BENZ SPRINTER, 2.1 D 316 CDI (W906) (M)	Engine No:	65195533604436
Reg. Date:	12/10/2017 (Man. Year: 2016)	Chassis No:	WDB9066332P302059
Colour:	Grey	Odometer:	30197 km
Engine Capacity:	2143 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/75 R16	Rear Tyre Size:	225/75 R16
Front Left Side:	Continental 9 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Continental 9 mm	Rear Right Side:	Continental 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,150.00	9,607.27	2,542.73	20.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,225.00	2,010.00	1,215.00	37.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,375.00</b>	<b>11,617.27</b>	<b>3,757.73</b>	<b>24.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,850.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,375.00</b>	<b>9,850.00</b>	<b>5,525.00</b>	<b>35.93</b>

INSPECTION

Date of Assignment:	27/09/2022		
Date Inspected:	28/09/2022	Inspected At:	Massive Trading & Auto - Amk (HQ) Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225
Estimated Period of Repair:	8.0 days		

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 18 Dec 2022)	
<b>Parts:</b>	N/A	MERCEDES-BENZ SPRINTER 2.1 D 316 CDI (W906) (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBL9475S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,550.00 FL	*1,218.00 FL
2	1		*FRONT O/S FENDER	Bent	750.00 FL	*473.75 FL
3	1		*FRONT O/S FENDER INNER PANEL	Bent	1,650.00 FL	*1,650.00 FL
4	1		*FRONT O/S FENDER INNERSHIELD	Distorted	205.00 FL	*205.00 FL
5	1		*FRONT O/S FENDER LAMP	Serviceable	195.00 FL	*- FL
6	1		*FRONT O/S HEADLAMP	Broken	855.00 FL	*830.00 FL
7	1		*FRONT GRILLE	Serviceable	625.00 FL	*- FL
8	1		*FRONT GRILLE FRAME	Serviceable	355.00 FL	*- FL
9	1		*FRONT SUPPORT PANEL	Cracked	675.00 FL	*675.00 FL
10	1		*FRONT O/S SUPPORT GARNISH	Distorted	105.00 FL	*105.00 FL
11	1		*FRONT BUMPER	Buckled	1,275.00 FL	*1,090.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	850.00 FL	*658.00 FL
13	1		*FRONT O/S BUMPER SIDE RETAINER	Distorted	175.00 FL	*175.00 FL
14	1		*FRONT O/S FOG LAMP	Missing	385.00 FL	*385.00 FL
15	1		*ABS PUMP	Cracked	3,850.00 FL	*3,210.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>13,500.00</b>	<b>10,674.75</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	1,350.00	1,067.48
<b>Total Parts (\$)</b>	<b>12,150.00</b>	<b>9,607.27</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE ACCIDENT PARTS INCLUDING KNOCKING WELDING & CUTTING ETC	New	1,400.00	900.00
2	TO PUTTY AND SPRAY PAINT -4 PORTIONS	New	1,200.00	750.00
3	CHECK & RECONNECT WIRING	New	45.00	20.00
4	TO RESPRAY ANTI-RUST PROOFING TREATMENT	New	120.00	90.00
5	REMOVE/REFIT AIR CON CONDENSER & TO TOP UP GAS	New	180.00	100.00
6	REMOVE /RENEW ABS PUMP AND TO RESET SAME	New	280.00	150.00
			<b>Gross Labour Cost (\$)</b>	<b>2,010.00</b>
				<b>3,225.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >