

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009526/KQY3Q2**Date:** 11/11/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00034292201	
Claimant Vehicle No :	SLK8506E	Insured Vehicle No :	XB2199C	
Date of Loss:	16/09/2022	Nature of Claim:	TP	Claim No: SNM22D206710/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK8506E		Engine No:	K9KG657R002072
Make & Model:	RENAULT MEGANE, 1.5 D Sedan DCI AT EU6 (M)		Chassis No:	VF1RFB00156020388
Reg. Date:	31/01/2017 (Man. Year: 2016)		Odometer:	123953 km
Colour:	White			
Engine Capacity:	1461 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,553.90	3,833.55	4,720.35	55.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	950.00	710.00	42.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,213.90	4,783.55	5,430.35	53.17
Approved Total (Overridden) (\$\$)		3,800.00		
Nett Amount (\$\$)	10,213.90	3,800.00	6,413.90	62.80

INSPECTION

Date of Assignment:	27/09/2022	LM AUTO SOLUTION PTE LTD (HQ) BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-12 Singapore 575645
Date Inspected:	28/09/2022 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Nov 2022)

Parts: 143 RENAULT MEGANE 1.5 D Sedan DCI AT EU6 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLK8506E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (NPA)	Repair	0.00 FL	*- FL
2	1		*FRONT BUMPER	Buckled	1,867.00 FL	*1,084.00 FL
3	1		*FRONT BUMPER RETAINER LH +RH	N/S Distorted	164.00 FL	*82.00 FL
4	2		*FRONT BUMPER BRACKET LH+RH	Repair	182.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	465.00 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Serviceable	155.00 FL	*- FL
7	1		*FRONT BUMPER GRILLE LH	Mtg Cracked	126.00 FL	*126.00 FL
8	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FL	*80.00 FL
9	1		*FRONT GRILLE ASSY	Mtg Cracked	858.00 FL	*701.40 FL
10	1		*SET FRONT GRILLE CLIP	Not Necessary	60.00 FL	*- FL
11	1		*FRONT FENDER LH	Buckled	963.00 FL	*711.80 FL
12	1		*FRONT FENDER COWLING LH	Cracked	189.00 FL	*189.00 FL
13	1		*FRONT FENDER GARNISH LH	Serviceable	67.00 FL	*- FL
14	1		*HEADLAMP ASSY LH	Cracked	2,986.00 FL	*1,285.30 FL
15	1		*FRONT RIM LH	Serviceable	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,962.00	4,259.50
- List Item Discount on L Items 5.00/10.00% (\$\$)	408.10	425.95
Total Parts (\$\$)	8,553.90	3,833.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK ,STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	New	600.00	400.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	800.00	440.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	60.00	30.00
4	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	100.00	20.00
5	TO CHECK WHEEL ALIGNMENT	New	100.00	60.00
Gross Labour Cost (\$\$)			1,660.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >