

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009528/KCY3Q2**Date:** 11/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00201832122

**Claimant Vehicle
No :** PC2274H**Insured Vehicle
No :** SY1323E

Date of Loss: 13/09/2022

Nature of Claim: TP

Claim
No: SNM22D206538/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **PC2274H**

Make & Model: YUTONG ZK6107H, 6.7 D (A)

Engine No: ISB67E525022101648

Reg. Date: 31/03/2014 (Man. Year: 2013)

Chassis No: LZYTBD6XD1064249

Colour: Multi-colour

Odometer: 414546 km

Engine Capacity: 6690 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size:

295/80 R22.5 (D)

Front Left Side: Giti 9 mm

Rear Left Side:

Akina 9/9 mm

Front Right Side: Giti 9 mm

Rear Right Side:

Akina 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	715.00	625.00	90.00	12.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	1,000.00	450.00	31.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,165.00	1,625.00	540.00	24.94
Approved Total (Overridden) (S\$)		1,050.00		
Nett Amount (S\$)	2,165.00	1,050.00	1,115.00	51.50

INSPECTION

Date of Assignment: 27/09/2022

Date Inspected: 28/09/2022 Inspected At:

Cheong Cheong Motor Service (HQ)
BLK 5032 ANG MO KIO INDUSTRIAL PARK 2
#01-293 SINGAPORE 569535
Singapore 569535

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 11 Oct 2022)	
Parts:	N/A	YUTONG ZK6107H 6.7 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC2274H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RIGHT SIDE SIGNAL LIGHT	Broken	80.00 FS	*80.00 FS
2	1		*LUGGAGE COMPARTMENT HANDLER RIGHT	Dented	230.00 FS	*230.00 FS
3	1		*EXCURSION BUS STICKER	Necessary	15.00 FS	*15.00 FS
4	1		*BODY STOPPER	Serviceable	90.00 FS	*- FS
5	1		*BODY LOWER BAR RIGHT	Bent	300.00 FS	*300.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					715.00	625.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE RENEW & REFIT ALL ACCIDENT DAMAGE PARTS & STRAIGHTEN ALL ACCIDENT AREAS & FIT ABOVE SAME	New	550.00	400.00
2	TO PUTTY & SPRAY PAINT & ANTI RUST ON ALL ACCIDENT DAMAGE PARTS & OTHERS ACCIDENT AFFECTED AREAS (2 TONS COLOUR)	New	900.00	600.00
Gross Labour Cost (\$\$)			1,450.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >