Adjuster Report 7/5/23, 3:42 PM

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16

Singapore 079120

Our File No:

CC3/AIG22009531/ACE2

Date:

05/07/2023

WAUZZZGA6LA002475

REFERENCE

Date of Loss:

Insured/Claimant:

ZHANG LING 04/03/2022

Policy No: Nature of Claim: 2070107971 OD

Engine No:

Chassis No:

Odometer:

Claim No:

CHZC35611

44705 km

0756833634SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SMT8483C

AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Make & Model:

21/07/2020 (Man. Year: 2019) Reg. Date:

Colour: Red 999 cc **Engine Capacity:**

Market Value/New Car

Price:

S\$128,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable): Yes

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

215/60 R16 Bridgestone 6 mm Rear Tyre Size: Rear Left Side:

215/60 R16 Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,000.00	1,884.80	9,115.20	82.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,152.00	1,602.00	1,550.00	49.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,152.00	3,486.80	10,665.20	75.36
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	13,352.00	2,686.80	10,665.20	79.88
+ GST 8.00/8.00% (S\$)	1,068.16	214.94	853.22	79.88
Nett Amount (S\$)	14,420.16	2,901.74	11,518.42	79.88

INSPECTION

Date of Assignment:

28/09/2022

Premium Automobiles Pte Ltd (UBI)

Date Inspected:

27/09/2022

Inspected At: 55 Ubi Road 1

Singapore 408699

Estimated Period of Repair:

3.0 days

Adjuster: **ADRIAN LING** Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,313.00 FS	*-FS
2	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	220.00 FS	*- FS
3	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	189.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE END CAP - RH	Not Necessary	66.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	332.00 FS	*- FS
6	1		*RADIATOR GRILLE	Cracked	1,561.00 FS	*1,248.80 FS
7	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	138.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	87.00 FS	*- FS
9	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	769.00 FS	*- FS
10	1		*HEADLIGHT - RH	Not Necessary	5,245.00 FS	*- FS
11	2		*FRONT WHEEL COVER - LH / RH	Necessary	720.00 FS	*576.00 FS
12	1		*FRONT NUMBER PLATE	Necessary	60.00 FS	*60.00 FS
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Fra	nchise	part. S=SpcN	lett.	_		
				Total Parts (S\$)	11,000.00	1,884.80

7/5/23, 3:42 PM Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO RESPRAY FRONT BUMPER	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE- ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
	Gross Labour Cost (S\$)		3,152.00	1,602.00
	Report was unsubmitted during this prin	nt-out.		

< END OF ESTIMATES >