

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22009535/UPA3Q2**Date:** 17/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800135339
Claimant Vehicle No :	SDJ6888R	Insured Vehicle No :	SME3633Z
Date of Loss:	27/09/2022	Nature of Claim:	TP
		Claim No:	5438542531SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDJ6888R	Engine No:	R16B25500753
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650JT000715
Reg. Date:	14/05/2018 (Man. Year: 2018)	Odometer:	125899 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	CST 7 mm	Rear Left Side:	CST 7 mm
Front Right Side:	CST 7 mm	Rear Right Side:	CST 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,801.92	1,261.20	540.72	30.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,510.00	750.00	760.00	50.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,311.92	2,011.20	1,300.72	39.27
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	3,311.92	1,600.00	1,711.92	51.69
+ GST 7.00/7.00% (S\$)	231.83	112.00	119.83	51.69
Nett Amount (S\$)	3,543.75	1,712.00	1,831.75	51.69
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
(S\$)		1,892.00		
Liabile Amount (50.00%) (S\$)		946.00		

INSPECTION

Date of Assignment:	17/10/2022		
Date Inspected:	17/10/2022	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH FENDER	Dented / Bent	450.80 FL	*450.80 FL
2	1		*FRT RH FENDER SIGNAL LAMP	Cracked	74.30 FL	*74.30 FL
3	1		*FRT BUMPER	Torn	549.90 FL	*549.90 FL
4	1		*FRT BUMPER SIDE RETAINER -RH	Bent	21.50 FL	*21.50 FL
5	1		*FRT HEADLAMP -RH	Not Necessary	675.90 FL	*- FL
6	1		*FRT RH RIM	Warped	480.00 FL	*480.00 FL
7	1		*FRT RH FENDERSHIELD (NPA)	Not Necessary	0.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,252.40	1,576.50
- List Item Discount on L Items 20.00/20.00% (S\$)	450.48	315.30
Total Parts (S\$)	1,801.92	1,261.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT WIRING	New	30.00	20.00
2	TO REMOVE AND RENEW PARTS	New	600.00	300.00
3	TO SPRAY PAINTING	New	800.00	400.00
4	TO APPLY UNDERCOATING	New	80.00	30.00
			Gross Labour Cost (\$\$)	750.00

1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >