

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SDJ 688R
 at Workshop m/s J.1 Park
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SDJ 688R Yr Regn: 14/05/18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA)
 Make: Honda Civic C.C. 1597
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 125899 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRHFC5650J T000715
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or
 Tyre Size: F: 215/45R17
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or CS7
 Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 27/09/22 D.O.I. 17/10/22
 Survey held at _____

Bal. or Market Value: \$80k.
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: LTA 36583
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 0/5 P +
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Rep 13k.
	agree 502
26/10/22	4/5 \$1600 in hand Jones.

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: : Site Insp (\$ _____) : S + RS, SI

: Interview (\$ _____) : Photos

: Tech. Invs (\$ _____) : Others

: Weekend (\$ _____)

TOTAL _____

JIN AUTO SERVICES PTE LTD

Blk 14 Defu Lane 10 #01-412
 Singapore 539195
 Tel:62894656 Fax :62870590
 Company Reg No:200704370C GST Reg No ::200704370C

Not Allowed
17/10/22
1/2 \$ 1600
4 days

17/10/2022

M/S AIG

DEAR SIR

ESTIMATE REPAIR COST FOR SDJ6888R

MR053HY9305130469

01)	1 PC	FRT RH FENDER	<i>os/ent</i>	\$	450.80	✓
02)	1 PC	FRT RH FENDER SIGNAL LAMP	<i>one</i>	\$	74.30	✓
03)	1 PC	FRT BUMPER	<i>to r</i>	\$	549.90	✓
04)	1 PC	FRT BUMPER SIDE RETAINER - RH	<i>ent</i>	\$	21.50	✓
05)	1 PC	FRT HEADLAMP - RH	<i>1 1</i>	\$	675.90	X
06)	1 PC	FRT RH RIM	<i>weped</i>	\$	480.00	✓
07)	1 PC	FRT RH FENDERSHIELD	<i>1 1</i>	\$	-	X

\$ 2,252.40

LESS 20% \$ (450.48)

\$ 1,801.92

08)	To remove and refit wiring	\$	30.00	<i>20</i>	
09)	To remove <i>remove</i> and renew parts	\$	600.00	<i>300</i>	
10)	To spray painting	\$	800.00	<i>400</i>	
11)	To apply undercoating	\$	80.00	<i>30</i>	
				\$	<u>3,311.92</u>

1576.50
202
1261.2
750
2011.2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: