

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22009540/UQY3Q2**Date:** 01/11/2022REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SMF2627T **Insured Vehicle No :** SJG8494A
 Date of Loss: 03/08/2022 Nature of Claim: TP Claim No: DMPC2200442H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF2627T**
 Make & Model: PEUGEOT 3008, 1.6 (A) Engine No: 10FJCC2465482
 Reg. Date: 31/10/2018 (Man. Year: 2018) Chassis No: VF3M45GZWJS268019
 Colour: Grey Odometer: 60959 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,523.86	653.71	1,870.15	74.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	400.00	800.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,723.86	1,053.71	2,670.15	71.70
+ GST 7.00/7.00% (S\$)	260.67	73.76	186.91	71.70
Nett Amount (S\$)	3,984.53	1,127.47	2,857.06	71.70

INSPECTION

Date of Assignment: 28/09/2022
 Date Inspected: 29/09/2022 Inspected At: LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ)
 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2022)
Parts:	144	PEUGEOT 3008 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF2627T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -LH	Repair	1,850.90 FL	*- FL
2	1		*FRONT DOOR PROTECTOR W/MOULDING	Scratched / Cracked	681.90 FL	*681.90 FL
3	1		*FRONT DOOR W/STRIP	Not Necessary	182.60 FL	*- FL
4	1		*SET FRONT DOOR PROTECTOR CLIP	Necessary	80.00 FS	*40.00 FS
					Sub Total (\$\$)	2,795.40 721.90
					- List Item Discount on L Items 10.00/10.00% (\$\$)	271.54 68.19
					Total Parts (\$\$)	2,523.86 653.71

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS	New	600.00	200.00
2	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACED DAMAGED PARTS	New	600.00	200.00
Gross Labour Cost (\$)			1,200.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >