11/11/22, 11:05 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG22009543/UQY3M4

11/11/2022 Date:

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001962443

**Claimant Vehicle** SMZ867A Insured Vehicle No: SMC1596X No:

Date of Loss: 26/09/2022 Nature of Claim: TP Claim No: 286192

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMZ867A

Make & Model: ALFA ROMEO GIULIA, 2.0 L (A) 1039083 Engine No:

Reg. Date: 13/03/2018 (Man. Year: 2018) Chassis No: ZAREAENN7H7565603

Colour: Odometer: 61470 km Black

**Engine Capacity:** 1995 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 225/40 R19 Rear Tyre Size: 255/357R19 Front Left Side: Rear Left Side: Michelin 7 mm Michelin 7 mm Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,462.32	0.00	5,462.32	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	850.00	2,510.00	74.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,822.32	850.00	7,972.32	90.37
+ GST 7.00/7.00% (S\$)	617.56	59.50	558.06	90.37
Nett Amount (S\$)	9,439.88	909.50	8,530.38	90.37

**INSPECTION** 

Date of Assignment: 28/09/2022

Specialists Motor Pte Ltd (HQ) Date Inspected: 30/09/2022 Inspected At:

Blk 3018A Ubi Road 1, #01-24/25/26

Singapore 408711

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Nov 2022)

Parts: 143 ALFA ROMEO GIULIA 2.0 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMZ867A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Repair	2,870.00 F	*- F
2	1		*SET REAR BUMPER CLIP	Not Necessary	80.00 F	*- F
3	2		*REAR BUMPER RETAINER LH&RH	Not Necessary	250.32 F	*- F
4	2		*REAR BUMPER PARKING SENSOR	Not Necessary	352.00 F	*- F
5	1		*REAR BUMPER DIFFUSER	Repair	1,830.00 F	*- F
6	1		*SET REAR BUMPER DIFFUSER CLIP	Not Necessary	80.00 F	*- F
F=Fra	anchise	part.		-		
				Total Parts (S\$)	5,462.32	0.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	KNOCKING, WELDING, REPLACE, RE-ALIGN REAR BUMPER FASCIA, REAR BUMPER LOWER LIP, REAR FENDER RH, TAIL LAMP RH, REAR BUMPER REINFORCEMENT BEAM, REAR BOOT COVER, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY	New	1,800.00	300.00
2	SPRAY PAINTING ON ALL AFFECTED PARTS	New	900.00	500.00
3	REMOVE & REFIX REAR BUMPER SENSOR	New	230.00	50.00
4	CHECK ALL LIGHTING AFTER REPAIRS	New	50.00	0.00
5	DIAGNOSIS & RESET	New	380.00	0.00
	Gross Labour Cost (S\$)		3,360.00	850.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >