



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 2536J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	RR BUMPER LH SIDE GUIDE (SN)	NOT NECESSARY	163.55	-
1	RR BUMPER RH SIDE GUIDE (SN)	NOT NECESSARY	163.55	-
1	SUPPORT (SN)	NOT NECESSARY	47.00	-
1	REAR BUMPER TRIM STRIP (BLACK) (SN)	CUT	90.30	90.30
1	REAR BUMPER PANEL PRIMED (LINES PDC (SN)	BROKEN	1,050.55	1,050.55
			1,664.95	1,220.85
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER.		1,700.00	850.00
	TO RESPRAY REAR BUMPER.		1,038.00	986.00
	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION.		177.00	168.00
	TO CHECK ELECTRICAL WIRING.		177.00	168.00
			3,092.00	2,172.00
	GRAND TOTAL		4,756.95	3,392.85
	RECOMMENDED COST OF REPAIRS			3,392.85

Report Ref No. CS/SMR22009544/Eny3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.