

27/9/2022

1st



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : PA9177U

Make & Model : TOYOTA HIACE

Year of Manufacture : 2009

Chassis No. : JTFJT02P100001297

Ins Company : ALLIANZ

Engine No. : 1KD2066530

Excess : _____

Policy No. : _____

Date of Accident : 11.09.2022

Time of Accident : 18:30

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : Johari BH

Signature : _____

Parts (a) Cost / List Price Items \$ 7,575.80

Plus/Less 30% \$ 2,272.74

Total of Cost / List \$ 5,303.06

(b) Nett Price Items _____

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 225.70

Total Parts Cost (Appendix A) \$ 5,528.76

Labour (Appendix B) \$ 3,020.00

Total Repair Cost \$ 8,548.76

Contact No

Frt Counter Operation

63837103 - Patrick Tia

PatrickTia@sparkcarcare.com

63837730 - Brenda Ng

BrendaNg@sparkcarcare.com

63837466 - Rohani

RohaniM@sparkcarcare.com

Workshop Operation

63837656 - Ngo Toh Wee

Ngotw@sparkcarcare.com

63838115 -

63837362 -

*Not authorized
L/Sy [redacted]
Prumny Alla Rainy*

The above total will be subjected to 7% G.S.T.

L/SUM 4,750.00

Name of Surveyor : Kenneth

Company : UKK

Survey conducted on : 28/9/22 at 1.15pm

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 0 Day day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 28/9/22

Spark Car Care
 ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : PA9177U Case Owner : Johari BH
 Make & Model : TOYOTA HIACE Year Manufactu : _____
 Chassis No : JTFJT02P100001297 Engine No : 1KD2066530
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR WINDSCREEN <i>1410.60 Shortland</i>	1		\$ 1,525.70			✓
2	REAR WINDSCREEN INNER SEAL	1			<i>MC</i>	\$ 60.00	<i>30sn</i>
	REAR WINDSCREEN SEALANT	1			<i>MC</i>	\$ 80.00	<i>40sn</i>
4	TAILGATE <i>1950.90 RY</i>	1		\$ 2,258.10			✓
5	TAILGATE ABSORBER <i>Sn</i>	2		\$ 556.60			X
6	TAILGATE EMBLEM <i>MC</i>	1		\$ 60.20			✓
7	TAILGATE GARNISH <i>RY</i>	1		\$ 158.30			✓
8	TAILGATE LOCK <i>Tm</i>	1		\$ 279.80			✓
9	TAILGATE CATCH <i>R</i>	1		\$ 107.20			X
10	TAILGATE UPPER HINGE <i>R</i>	2		\$ 150.40			X
11	TAILGATE NUMBER PLATE LAMP <i>Sn</i>	2		\$ 146.60			X
12	70KM/H STICKER	1			<i>MC</i>	\$ 35.70	<i>15sn</i>
13	TAIL LAMP <i>e277.60 d/s Rn MSN</i>	X2		\$ 734.20			<i>L</i>
14	REAR BUMPER <i>RY</i>	1		\$ 485.20			✓
15	REAR BUMPER SIDE BRACKET <i>d/s RY</i>	2		\$ 84.20			<i>L</i>
16	REAR BUMPER LOWER BRACKET <i>DIT</i>	4		\$ 146.80			✓
17	END PANEL <i>RY</i>	1		\$ 386.70			✓
	END PANEL TOP GARNISH <i>Sn</i>	1		\$ 115.80			X
19	REVERSE SENSOR	1SET		\$ 380.00			<i>200sn</i>
20	NUMBER PLATE	1			<i>MC</i>	\$ 50.00	<i>25sn</i>
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No. : PA9177U
 Make & Model : TOYOTA HIACE

Case Owner : Johari BH
 Year of Manufacture : 2009

S/No	Labour Description	Estimated Price	Adjusted Price
	To knock & straighten on accident area, to remove & refit damage parts.	\$1,000.00	900
	To putty & respray on rear both fender, rear floor panel, rear end panel tailgate and affected area.	\$1,400.00	800
	To transfer of tailgate fittings, fixture and perform waterseepage test.	\$140.00	80
	To install of rear bumper sensor.	\$100.00	50
	To rust proof the affected area	\$380.00	60
	76 Kerosen per mesin	\$120	✓
<div style="border: 1px solid black; padding: 5px;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>			

The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.