



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 1568G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	NUMBER PLATE WITH CASING-L(N) (SN)	NOT NECESSARY	45.00	-
4	SENSOR ASSYPARKING (SN)	CUT (2PCS ONLY)	284.40	142.20
1	FACE ASSYRR.BUMPER (SN)	BROKEN	472.87	472.87
1	REFLECTOR ASSYL.RR (SN)	MISSING	22.80	22.80
1	GARNISHRR.BUMPER LOWER (SN)	NOT NECESSARY	64.35	-
1	MOULDINGRR.BUMPER (SN)	BROKEN	169.27	169.27
1	BRACKETR.RR.BUMPER (SN)	NOT NECESSARY	5.25	-
1	BRACKETL.RR.BUMPER (SN)	NOT NECESSARY	4.35	-
1	PROTECTORRR.BUMPER SIDE (SN)	NOT NECESSARY	19.72	-
1	BEAM COMP,RR BPR (SN)	BENT	252.45	252.45
1	SPACERR.RR.BUMPER SIDE (SN)	BROKEN	10.57	10.57
1	SPACERL.RR.BUMPER SIDE (SN)	BROKEN	10.57	10.57
4	CLIP, BUMPER (SN)	NECESSARY	6.90	6.90
1	LID COMPTRUNK (SN)	DENTED	758.40	758.40
1	WEATHERSTRIPTRUNKLID (SN)	NOT NECESSARY	61.72	-
1	EMBLEMH (SN)	NECESSARY	23.10	23.10
1	EMBLEMRR.ACCORD (SN)	NECESSARY	16.65	16.65
1	EMBLEMRR.I-VTEC (SN)	NECESSARY	29.55	29.55
1	PAN COMPSPARE TIRE (SN)	NOT NECESSARY	291.30	-
1	PANEL COMPRR. (SN)	DENTED	349.27	349.27
1	LINING ASSYRR.PANEL (SN)	NOT NECESSARY	67.57	-
1	EMBLEMFR. (SN)	NOT NECESSARY	23.10	-
1	NUT, PUSH 3MM (SN)	NOT NECESSARY	1.57	-
12	CLIP, BUMPER (SN)	NOT NECESSARY	20.70	-
1	LIGHT ASSYL.LID (LH) (SN)	CUT	355.50	355.50
1	SUNDRIES (SN)	NECESSARY	110.00	30.00
9	CLIP, INNER FENDER (SN)	NOT NECESSARY	18.90	-
			3,495.83	2,650.10
<u>LABOUR</u>				
	BODY JOINT SEALANT.		120.00	120.00

Report Ref No. CS/SMR22009564/Evy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	BODY UNDERSIDE COATING (N).		520.00	520.00
	APPLY BODY UNDERSIDE COATING (N).	NOT NECESSARY	520.00	-
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		250.00	180.00
	REMOVE & INSTALL REVERSE SENSORS - 4PCS (N).		250.00	180.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA.		650.00	580.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		650.00	650.00
	REMOVE & INSTALL EXHAUST SYSTEM. (N)	NOT NECESSARY	650.00	-
	REMOVE & INSTALL FUEL TANK FUEL PIPES. (N)	NOT NECESSARY	650.00	-
	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID.		650.00	580.00
	REMOVE & RENEW RR FLOOR INSULATOR.(N)	NOT NECESSARY	650.00	-
	CUT & RENEW RR FLOOR PANEL CUT LH FENDERS ALIG.		4,000.00	2,600.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P)		3,500.00	2,600.00
	TOWING SERVICES (MBBS).		150.00	150.00
	RESET VEHICLE SMART ENTRY SYSTEM. (ADDITIONAL)		580.00	110.00
			13,790.00	8,270.00
GRAND TOTAL			17,285.83	10,920.10
RECOMMENDED COST OF REPAIRS				10,920.10

Report Ref No. CS/SMR22009564/Evy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.