

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009578/UWY3Q2**Date:** 02/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00051942200

**Claimant Vehicle
No :** FBK4813M**Insured
Vehicle No :** YQ3453X

Date of Loss: 22/09/2022

Nature of Claim: TP

Claim
No: SNM22D206885/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **FBK4813M**

Make & Model: YAMAHA FZ150, 150cc

Engine No: G3E3E0004779

Reg. Date: 15/09/2015 (Man. Year: 2015)

Chassis No: ME1RG1612F2001500

Colour: Black

Odometer: 81539 km

Engine Capacity: 149 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/80-17

Rear Tyre Size:

130/70-17

Front Left Side: Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,321.00	873.10	2,447.90	73.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	756.00	250.00	506.00	66.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,077.00	1,123.10	2,953.90	72.45
Approved Total (Overridden) (S\$)		900.00		
(S\$)	4,077.00	900.00	3,177.00	77.92
+ GST 7.00/7.00% (S\$)	285.39	63.00	222.39	77.92
Nett Amount (S\$)	4,362.39	963.00	3,399.39	77.92

INSPECTION

Date of Assignment: 28/09/2022

Date Inspected: 28/09/2022

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Dec 2022)	
Parts:	N/A	YAMAHA FZ150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK4813M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*AXLE WHEEL FRONT	Serviceable	29.00 F	*- FL
2	1	*BALANCER HANDLE (BLACK)	Missing	16.00 F	*16.00 FL
3	1	*BAR FOOTREST FRONT LH	Cut	16.00 F	*16.00 FL
4	1	*BAR HANDLE	Bent	48.00 F	*48.00 FL
5	1	*BOLT FOOTREST REAR	Cut	6.00 F	*6.00 FL
6	1	*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Cut	230.00 F	*230.00 FL
7	1	*BRACKET FOOTREST LH	Not Necessary	48.00 F	*- FL
8	1	*COVER HEADLAMP RH (Cracked)	Not Consistent With The Impact	73.00 F	*- FL
9	1	*COVER INNER MUDGUARD	Cracked	42.00 F	*42.00 FL
10	1	*COVER OUTER 1 (Cut)	Not Consistent With The Impact	35.00 F	*- FL
11	1	*COVER REAR FENDER	Broken	38.00 F	*38.00 FL
12	1	*COVER REAR FENDER 1	Broken	20.00 F	*20.00 FL
13	1	*COVER SIDE 1 (Cut)	Not Consistent With The Impact	38.00 F	*- FL
14	1	*COVER SIDE LH	Cracked	56.00 F	*56.00 FL
15	1	*COVER TAIL LH (BLACK)	Cracked	68.00 F	*68.00 FL
16	1	*COVER TANK SIDE LH (BLACK)	Repair	138.00 F	*- FL
17	1	*DAMPER	Not Necessary	5.00 F	*- FL
18	1	*FOOTREST REAR 1	Cut	13.00 F	*13.00 FL
19	1	*SET FORK ASSY (Bent)	Not Consistent With The Impact	1,192.00 F	*- FL
20	1	*GRIP HANDLE LH	Torn	12.00 F	*12.00 FL
21	1	*GUARD CHAIN	Not Necessary	12.00 F	*- FL
22	1	*GUIDE AIR 1	Not Necessary	100.00 F	*- FL
23	1	*HEADLIGHT ASSY (Scratched)	Not Consistent With The Impact	160.00 F	*- FL
24	1	*HOLDER LEVER CLUTCH	Cracked	18.00 F	*18.00 FL
25	1	*LAMP SIGNAL FRONT RH	Not Necessary	24.00 F	*- FL
26	1	*LEVER CLUTCH	Cut	18.00 F	*18.00 FL
27	1	*METER IU (12V) NEW MODEL (Cut)	Not Consistent With The Impact	280.00 F	*- FL
28	1	*MIRROR ASSY (LH)	Cut	32.00 F	*32.00 FL
29	1	*MUDGUARD FRONT (BLACK)	Broken	112.00 F	*112.00 FL
30	1	*PLATE NUMBER FRONT (STRAIGHT) (Bent)	Not Consistent With The Impact	23.00 F	*- FL
31	1	*PLATE NUMBER REAR (6.5 INCH X 9 INCH)	Bent	29.00 FS	*10.00 FS
32	1	*REAR FLASHER LIGHT ASSY 1	Damaged	20.00 F	*20.00 FL
33	1	*REAR FLASHER LIGHT ASSY 2	Missing	20.00 F	*20.00 FL
34	1	*REFLECTOR REAR FENDER	Missing	9.00 F	*9.00 FL
35	1	*RUBBER FOOTREST FRONT	Cut	10.00 F	*10.00 FL
36	1	*SHIFT PEDAL ASSY	Not Necessary	42.00 F	*- FL
37	1	*SIDE STAND	Cracked	25.00 F	*25.00 FL
38	1	*SIGNAL ASSY FRONT LH	Serviceable	24.00 F	*- FL
39	1	*SPRING TENSION	Not Necessary	8.00 F	*- FL
40	1	*STAY 1	Not Necessary	16.00 F	*- FL
41	1	*STAY 2	Not Necessary	38.00 F	*- FL
42	1	*STAY REAR RH	Bent	55.00 F	*55.00 FL
43	1	*SET STEERING CONE	Not Necessary	48.00 F	*- FL
44	1	*SWITCH HANDLE 4	Cracked	58.00 F	*58.00 FL
45	1	*SPRING SIDE STAND	Damaged	17.00 F	*17.00 FL

Report was unsubmitted during this print-out.

12/2/22, 10:50 AMAdjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					3,321.00	969.00
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	95.90
Total Parts (S\$)					3,321.00	873.10
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	756.00	250.00
Gross Labour Cost (\$)			756.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >