

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122009580/DQY3Q2**Date:** 16/03/2023REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SHC3061T **Insured Vehicle No :** SLB99M

Date of Loss: 28/09/2022 Nature of Claim: TP Claim No: CDMPG22002020

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC3061T**

Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A) Engine No: G4LEJU167737

Reg. Date: 01/02/2019 (Man. Year: 2018) Chassis No: KMHC851CVKU134053

Colour: Blue Odometer: 571958 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,902.78	23,358.96	13,543.82	36.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,410.00	2,270.00	3,140.00	58.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,312.78	25,628.96	16,683.82	39.43
Approved Total (Overridden) (S\$)		20,500.00		
(S\$)	42,312.78	20,500.00	21,812.78	51.55
+ GST 8.00/8.00% (S\$)	3,385.02	1,640.00	1,745.02	51.55
Nett Amount (S\$)	45,697.80	22,140.00	23,557.80	51.55

INSPECTION

Date of Assignment: 28/09/2022

Date Inspected: 29/09/2022 Inspected At: 8 KAKI BUKIT AVENUE 4
#01-49 PREMIER @ KAKI BUKIT
SINGAPORE 415875

Estimated Period of Repair: 10.0 days Repairer: Bifrost Auto Pte Ltd (sin Ming) (HQ)10

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2023)
Parts: 143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC3061T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,253.80 FL	*2,253.80 FL
2	2		*BONNET HINGE (LH/RH)	Not Necessary	237.40 FL	*- FL
3	1		*BONNET MOULDING	Not Necessary	41.40 FL	*- FL
4	1		*BONNET LOCK	Repair	127.30 FL	*- FL
5	1		*BONNET INSULATOR	Serviceable	230.10 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	15.00 FL	*- FL
7	1		*RADIATOR GRILLE NEW MODEL	Broken	1,568.60 FL	*1,568.60 FL
8	2		*FLAP ASSY ACTIVE AIR UPPER (LH/RH)	Broken	1,649.20 FL	*1,649.20 FL
9	1		*SPEAKER ASSY -VESS	Not Necessary	554.40 FL	*- FL
10	1		*UNIT ASSY -SMART ERU (RADAR SENSOR)	Mtg Broken	3,061.40 FL	*2,910.90 FL
11	1		*FRONT NUMBER PLATE GARNISH	Not Necessary	188.00 FL	*- FL
12	1		*FRONT BUMPER COVER	Cracked	481.10 FL	*481.10 FL
13	1		*FRONT BUMPER TOP COVER	Bent	476.30 FL	*476.30 FL
14	1		*FRONT BUMPER SPONGE	Torn	186.90 FL	*186.90 FL
15	1		*FRONT BUMPER REINFORCEMENT	Bent	1,136.70 FL	*1,136.70 FL
16	2		*FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH)	Not Necessary	373.00 FL	*- FL
17	1		*FRONT BUMPER MOULDING CENTRE UPPER	Cut	368.50 FL	*368.50 FL
18	1		*FRONT BUMPER MOULDING	Not Necessary	93.60 FL	*- FL
19	1		*FRONT BUMPER LOWER STIFFNER	Not Necessary	285.10 FL	*- FL
20	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	365.30 FL	*- FL
21	1		*FRONT BUMPER LOWER GRILLE MOULDING	Not Necessary	127.60 FL	*- FL
22	1		*FRONT BUMPER LIP	Not Necessary	35.10 FL	*- FL
23	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	70.00 FL	*- FL
24	2		*FRONT BUMPER BRACKET (LH/RH)	Serviceable	56.00 FL	*- FL
25	2		*FRONT BUMPER RETAINER MOUNTING (LH/RH)	Not Necessary	130.60 FL	*- FL
26	1		*FRONT BUMPER CLIPS	Necessary	25.00 FL	*25.00 FL
27	2		*FRONT BUMPER GRILLE (LH/RH)	Not Necessary	373.80 FL	*- FL
28	2		*FRONT BUMPER AIR DUCT (LH/RH)	Not Necessary	307.60 FL	*- FL
29	1		*DAY LIGHT ,LH	Not Necessary	642.50 FL	*- FL
30	1		*DAY LIGHT ,RH	Not Necessary	642.50 FL	*- FL
31	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	1,139.30 FL	*1,139.30 FL
32	2		*HEADLAMP (LH/RH)	Broken	7,974.60 FL	*3,987.30 FL
33	1		*RADIATOR INVERTER	Bent	884.80 FL	*884.80 FL
34	1		*RADIATOR	Bent	710.50 FL	*710.50 FL
35	1		*RADIATOR FAN BLOWER MOTOR ASSY	Not Necessary	1,459.60 FL	*- FL
36	2		*RADIATOR AIR GUARD (LH/RH)	Serviceable	152.80 FL	*- FL
37	2		*RADIATOR AIR GUARD,UPR (LH/RH)	Not Necessary	255.00 FL	*- FL
38	1		*FRONT FENDER (RH)	Repair	490.70 FL	*- FL
39	1		*FRONT FENDER SHIELD (RH)	Not Necessary	164.70 FL	*- FL
40	1		*AIRCON CONDENSER	Bent	663.60 FL	*663.60 FL
41	1		*WIPER CONTAINER ASSY	Not Necessary	385.40 FL	*- FL
42	1		*BOOT LID	Dented	2,549.70 FL	*2,549.70 FL
43	1		*BOOT LID RUBBER	Deformed / Necessary	187.40 FL	*187.40 FL
44	2		*BOOT LID HINGE (LH/RH)	Not Necessary	142.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	2		*BOOT LID ABSORBER (LH/RH)	Not Necessary	173.40 FL	*- FL
46	1		*BOOT LID LOCK UPPER	Damaged	224.00 FL	*224.00 FL
47	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
48	1		*EMBLEM -HYBRID	Necessary	24.30 FL	*24.30 FL
49	1		*EMBLEM -LONIQ	Necessary	31.30 FL	*31.30 FL
50	1		*REAR SPOILER	Not Necessary	665.40 FL	*- FL
51	2		*BOOT LID LAMP (LH/RH)	Mtg Cracked	1,644.00 FL	*1,588.80 FL
52	1		*BOOT LID TRIMBOARD	Not Necessary	259.70 FL	*- FL
53	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
54	1		*BOOT LID GLASS UPPER MOULDING	Not Necessary	186.30 FL	*- FL
55	1		*BOOT LID GLASS LOWER MOULDING	Not Necessary	145.20 FL	*- FL
56	1		*REAR BUMPER	Distorted	459.40 FL	*459.40 FL
57	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
58	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent	376.20 FL	*376.20 FL
59	1		*ANTENNA ASSY -SMARTK OUTER	Mtg Broken	689.50 FL	*689.50 FL
60	1		*REAR BUMPER CENTRE MOULDING ASSY	Distorted	451.25 FL	*451.25 FL
61	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Mtg Broken	155.00 FL	*155.00 FL
62	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
63	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Serviceable	171.60 FL	*- FL
64	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
65	1		*REAR BUMPER UNDER CENTRE	Cracked	123.85 FL	*123.85 FL
66	2		*REAR BUMPER SIDE UNDER (LH/RH)	Serviceable	246.20 FL	*- FL
67	2		*REAR BUMPER REAR HOOK	Not Necessary	189.20 FL	*- FL
68	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	165.80 FL	*- FL
69	1		*REAR BUMPER REVERSE LIGHT (PARKING BRAKE LIGHT)	Socket Broken	328.60 FL	*328.60 FL
70	1		*LICENCE LAMP	Not Necessary	193.53 FL	*- FL
71	2		*TAIL LAMP (LH/RH)	Mtg Broken	1,870.80 FL	*1,740.80 FL
72	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
73	1		*ANTENNA ASSY -TRUNK	Not Necessary	689.50 FL	*- FL
74	1		*REAR PANEL GARNISH	Deformed	346.80 FL	*346.80 FL
75	1		*FRONT NUMBER PLATE	Not Necessary	25.00 FS	*- FS
76	1		*FRONT NO PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
77	1		*COOLANT	Not Necessary	45.00 FS	*- FS
78	1		*EMBLEM -BLUE DRIVE (RH)	Not Necessary	26.60 FS	*- FS
79	1		*REVERSE CAMERA ASSY	Not Necessary	983.20 FS	*- FS
80	1		*BOOT LID COMFORT LOGO & TEL NO.STICKER	Necessary	35.00 FS	*35.00 FS
81	1		*BOOT LID COMFORT CABLINK TEL NO.STICKER	Not fitted	30.00 FS	*- FS
82	1		*REAR NO PLATE+TRIM COVER	Cracked / Dented	45.00 FS	*45.00 FS
83	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 FS	*92.00 FS
84	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
85	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 45,743.03 29,098.20
- List Item Discount on L Items 20.00/20.00% (\$\$) 8,840.25 5,739.24

Total Parts (\$\$) 36,902.78 23,358.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	900.00
2	SPRAY PAINTING CHARGE	New	1,800.00	900.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE/REFIX RADIATOR	New	90.00	50.00
9	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	80.00
10	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	150.00
Gross Labour Cost (S\$)			5,410.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >