

Vehicle Damage Assessment Report for [SHC3061T]

Estimate Created: 09/03/2023 14:59 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 09/03/2023 16:06 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Hyundai	Model	Ioniq
Engine Type			
License Plate Number	SHC3061T	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$20,500.00 WITH 10 WORKING DAYS

Insurlogic 4 (09/03/2023 16:06)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
bonnet		1	2253.80	-20.00 %	1,803.04
radiator grille		1	1568.60	-20.00 %	1,254.88
Flap assy active air upper (LH/RH)		2	824.60	-20.00 %	1,319.36
Unit assy - SMART CRU (radar sensor)		1	2910.90	-20.00 %	2,328.72
front bumper cover		1	481.10	-20.00 %	384.88
front bumper top cover		1	476.30	-20.00 %	381.04
front bumper sponge		1	186.90	-20.00 %	149.52
front bumper reinforcement		1	1136.70	-20.00 %	909.36
front bumper moulding centre upper		1	368.50	-20.00 %	294.80
front bumper clips		1	25.00	-20.00 %	20.00
headlamp support panel assy		1	1139.30	-20.00 %	911.44
headlamp (LH/RH)		2	1993.65	-20.00 %	3,189.84
radiator inverter		1	884.80	-20.00 %	707.84
radiator		1	710.50	-20.00 %	568.40
aircon condenser		1	663.60	-20.00 %	530.88
bootlid		1	2549.70	-20.00 %	2,039.76
bootlid rubber		1	187.40	-20.00 %	149.92
bootlid lock upper		1	224.00	-20.00 %	179.20
bootlid H emblem		1	28.00	-20.00 %	22.40
bootlid Hybrid emblem		1	24.30	-20.00 %	19.44
bootlid Ioniq emblem		1	31.30	-20.00 %	25.04
bootlid lamp (LH/RH)		2	794.40	-20.00 %	1,271.04
rear bumper		1	459.40	-20.00 %	367.52
rear bumper reinforcement		1	394.80	-20.00 %	315.84
rear bumper reinforcement bracket (LH/RH)		2	188.10	-20.00 %	300.96
Antenna assy - SMART outer		1	689.50	-20.00 %	551.60
rear bumper center moulding assy		1	451.25	-20.00 %	361.00
rear bumper lower centre moulding assy		1	155.00	-20.00 %	124.00
rear bumper cover clips		1	22.00	-20.00 %	17.60
rear bumper under center		1	123.85	-20.00 %	99.08
rear bumper reverse light (parking brake light)		1	328.60	-20.00 %	262.88
taillamp (LH/RH)		2	870.40	-20.00 %	1,392.64
rear panel		1	532.00	-20.00 %	425.60

rear panel garnish	1	346.80	-20.00 %	277.44
--------------------	---	--------	----------	--------

Parts Subtotal 22,956.96

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Bootlid Comfort Logo & Tel No. sticker		1.0	35.00	0.00 %	35.00
Rear No. plate + Trim cover		1.0	45.00	0.00 %	45.00
Rear windscreen sealant		1.0	92.00	0.00 %	92.00
Rear Bumper Rubber Mat		1.0	50.00	0.00 %	50.00
Rear bumper Reverse Sensor		1.0	180.00	0.00 %	180.00

Materials Subtotal 402.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	900.00	0.00 %	900.00
Wiring charge	RnR	30.00	0.00 %	30.00
Tuff Coat	RnR	40.00	0.00 %	40.00
Remove and Refix rear windscreen glass	RnR	80.00	0.00 %	80.00
Remove/Refix Reverse sensor	RnR	40.00	0.00 %	40.00
Remove/Refix radiator	RnR	50.00	0.00 %	50.00
Remove/Refix aircon & refill aircon gas	RnR	80.00	0.00 %	80.00
Diagnostic & resetting to erase fault code	RnR	150.00	0.00 %	150.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	900.00	0.00 %	900.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,370.00

Paint Labor Subtotal 900.00

Labor Subtotal 2,270.00

Summary

Repair Cost 25,628.96

Discount(20 %) (5,125.79)

20,503.17

Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	20,503.17