



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 8969S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,031.00	1,031.00
1	FRONT BUMPER LH LAMP	NOT NECESSARY	155.00	-
1	FRONT BUMPER LH LAMP COVER	NOT NECESSARY	72.00	-
2	FRONT BUMPER SIDE RETAINER L/R @\$18.90	N/S DAMAGED	37.80	18.90
1	FRONT LH FENDER	DENTED	350.00	350.00
1	FRONT LH FENDER INNER SHIELD	TORN	145.00	145.00
1	FRONT LH HEADLAMP	CRACKED	1,070.00	1,070.00
1	FRONT LH KNUCKLE ARM	NOT NECESSARY	405.00	-
1	FRONT LH KNUCKLE ARM BEARING	DAMAGED	568.00	568.00
1	FRONT LH LINKAGE	NOT NECESSARY	64.70	-
1	FRONT LH LOWER ARM	BENT	509.00	509.00
1	FRONT LH SHOCK ABSORBER	NOT NECESSARY	360.00	-
1	FRONT LH SHOCK ABSORBER MOUNTING	NOT NECESSARY	91.00	-
	LESS 20% DISCOUNT		-971.70	-738.38
			3,886.80	2,953.52
1	FRONT LH SPORT RIM (SN)	CUT	1,162.00	650.00
	LESS 20% DISCOUNT		-232.40	-
			929.60	650.00
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET FRONT LH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT LH TYRE (SN)	NOT NECESSARY	380.00	-
			480.00	60.00
<u>LABOUR</u>				
	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING (TO FR).		60.00	30.00
	TO REMOVE ,REINSTALL FRONT SUSPENSION UNDERCARRIAGE PARTS (TO FR).		220.00	150.00
	TO ROAD TEST DRIVING ,CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM.		100.00	80.00

Report Ref No. CS/AGI22009584/Avy3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT .		600.00	400.00
	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		600.00	500.00
	TO APPLY ANTI -RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		50.00	40.00
			1,630.00	1,200.00
	GRAND TOTAL		6,926.40	4,863.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,900.00

Report Ref No. CS/AGI22009584/Avy3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.