

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22009586/SPA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF1000000531

Claimant Vehicle No : SLB8927X **Insured Vehicle No :** SMQ4424R

Date of Loss: 11/09/2022 Nature of Claim: TP Claim No: FRCAISCL2022-0002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB8927X**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZR560811

Reg. Date: 26/04/2016 (Man. Year: 2016) Chassis No: MR053REH104548443

Colour: Blue Odometer: 39322 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,861.19	612.50	2,248.69	78.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	860.00	1,840.00	68.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,561.19	1,472.50	4,088.69	73.52
Approved Total (Overridden) (\$\$)		1,180.00		
Nett Amount (\$\$)	5,561.19	1,180.00	4,381.19	78.78
+ Car Rental (2.0 x S\$100.00/day) (\$\$)		200.00		
Nett Liability (\$\$)		1,380.00		

INSPECTION

Date of Assignment: 28/09/2022

Date Inspected: 03/10/2022 Inspected At: MHL AUTOMOBILE SERVICES (HQ)
BLK 3006 UBI ROAD 1 #01-360
Singapore 408700

Estimated Period of Repair: 2.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2023)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB8927X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	794.00 FL	*620.00 FL
2	2		*REAR BUMPER REFLECTOR	Not Necessary	54.20 FL	*- FL
3	1		*REAR BUMPER SENSOR	Not Necessary	195.00 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER	Cracked	130.00 FL	*130.00 FL
5	1		*REAR BUMPER SPONGE	Not Necessary	121.30 FL	*- FL
6	1		*REAR BUMPER RE ENFORCEMENT	Repair	235.20 FL	*- FL
7	1		*BOOT LID LOGO	Not Necessary	89.70 FL	*- FL
8	2		*BOOT LID EMBLEM ALTIS	Not Necessary	75.70 FL	*- FL
9	1		*BOOT LID EMBLEM COROLLA	Not Necessary	80.30 FL	*- FL
10	1		*BOOT LID RH REFLECTOR	Not Necessary	288.70 FL	*- FL
11	1		*RH TAILLAMP	Not Necessary	380.10 FL	*- FL
12	1		*REAR MUFFLER	Not Necessary	1,237.39 FL	*- FL
13	1		*SETS REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
14	1		*SETS REAR RH FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,781.59	800.00
- List Item Discount on L Items 25.00/25.00% (S\$)	920.40	187.50
Total Parts (S\$)	2,861.19	612.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	100.00	30.00
2	TO TRANSFER REAR BUMPER SENSOR ATTACHMENT	New	100.00	30.00
3	TO R&R REAR INNER TRIM FOR HOT WORK REPAIR	New	200.00	0.00
4	TO CARRY OUT BODY CAVITY PRESERVATION	New	200.00	0.00
5	TO RESET AND REPROGRAME AFTER REPAIR THE VEHICLE	New	200.00	0.00
6	TO R&R REAR MUFFLER	New	100.00	0.00
7	LABOUR CHARGES	New	800.00	400.00
8	SPRAY PAINTING	New	1,000.00	400.00
Gross Labour Cost (S\$)			2,700.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >