

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22009587/AQY3E2**Date:** 20/12/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002746429-01
Claimant Vehicle No :	SMR4877L	Insured Vehicle No :	EY10E
Date of Loss:	23/09/2022	Nature of Claim:	TP
		Claim No:	202222007015SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR4877L		
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Engine No:	27491030287981
Reg. Date:	29/01/2015 (Man. Year: 2014)	Chassis No:	WDD2050402R026397
Colour:	Red	Odometer:	167032 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,469.10	13,236.00	5,233.10	28.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,240.00	990.00	44.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,699.10	14,476.00	6,223.10	30.06
Approved Total (Overridden) (S\$)		11,500.00		
(S\$)	20,699.10	11,500.00	9,199.10	44.44
+ GST 7.00/7.00% (S\$)	1,448.94	805.00	643.94	44.44
Nett Amount (S\$)	22,148.04	12,305.00	9,843.04	44.44
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	28/09/2022	
Date Inspected:	29/09/2022 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2022)
Parts:	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR4877L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,698.00 FL	*- FL
2	1		*FRONT BUMPER RH INNER SIDE BRACKET	Not Necessary	115.00 FL	*- FL
3	1		*FRONT BUMPER RIVET (15 PCS)	Necessary	135.00 FL	*50.00 FL
4	2		*FRONT BUMPER SIDE RETAINER L/R	Not Necessary	48.00 FL	*- FL
5	1		*FRONT RH HEADLAMP	Cracked	3,580.00 FL	*3,300.00 FL
6	1		*FRONT RH KNUCKLE ARM	Damaged	1,370.00 FL	*1,289.00 FL
7	1		*FRONT RH KNUCKLE ARM BEARING	Damaged	598.00 FL	*465.00 FL
8	1		*FRONT RH LINKAGE	Not Necessary	105.00 FL	*- FL
9	1		*FRONT RH LOWER ARM	Bent	685.00 FL	*472.00 FL
10	1		*FRONT RH LOWER ARM STARY ARM	Bent	674.00 FL	*458.00 FL
11	1		*FRONT RH SHOCK ABSORBER	Bent	805.00 FL	*697.00 FL
12	1		*FRONT RH SHOCK ABSORBER MOUNTING	Not Necessary	295.00 FL	*- FL
13	1		*FRONT RH SHOCK ABSORBER RUBBER	Not Necessary	36.00 FL	*- FL
14	1		*FRONT RH SHOCK ABSORBER SPONGE	Not Necessary	92.00 FL	*- FL
15	1		*FRONT RH SPORT RIM	Cut	650.00 FL	*650.00 FL
16	1		*FRONT RH UPPER ARM	Not Necessary	898.00 FL	*- FL
17	1		*STEERING RACK & PINION ASSY	Bent	8,015.00 FL	*6,959.00 FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
19	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
20	1		*FRONT RH TYRE	Torn	550.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,449.00	14,670.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,979.90	1,434.00
Total Parts (\$\$)	18,469.10	13,236.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	250.00	180.00
2	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE ,CHARGE FRONT SUSPENSION PARTS ,ABSORBER ,LOWER ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB ,DRIVE SHAFT ,ANTI-ROLL BAR ,TOP-ARM AND STEERING RACK AND PINION	New	550.00	350.00
4	TO ROAD TEST DRIVING CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	150.00	80.00
5	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	600.00	250.00
6	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	600.00	300.00
Gross Labour Cost (\$\$)			2,230.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >