

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIS22009589/KPA3Q2**Date:** 19/04/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SPMF1000000503

**Claimant Vehicle No :** XD9160G **Insured Vehicle No :** SLV1072C

Date of Loss: 24/09/2022 Nature of Claim: TP Claim No: SEVAISCL2022-0023-JK

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **XD9160G**  
 Make & Model: VOLVO FMX370, 10.8 D 64R DAYCAB (M) Engine No: D11300012  
 Reg. Date: 17/06/2014 (Man. Year: 2013) Chassis No: YV2J1E1D5DA750838  
 Colour: Maroon Odometer: 630466 km  
 Engine Capacity: 10837 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D/D)  
 Front Left Side: Triangle 9 mm Rear Left Side: Triangle 7/7/7/7 mm  
 Front Right Side: Triangle 9 mm Rear Right Side: Triangle 7/7/7/7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,256.50	13,596.25	5,660.25	29.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,440.00	3,480.00	5,960.00	63.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>28,696.50</b>	<b>17,076.25</b>	<b>11,620.25</b>	<b>40.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>13,500.00</b>		
<b>(S\$)</b>	28,696.50	13,500.00	15,196.50	52.96
<b>+ GST 7.00/7.00% (S\$)</b>	2,008.76	945.00	1,063.76	52.96
<b>Nett Amount (S\$)</b>	<b>30,705.26</b>	<b>14,445.00</b>	<b>16,260.26</b>	<b>52.96</b>
<b>+ Loss of Use (7.0 x S\$150.00/day) (S\$)</b>		1,050.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>15,502.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>15,500.00</b>		

**INSPECTION**

Date of Assignment: 28/09/2022

Date Inspected: 29/09/2022 Inspected At:

Sc Auto Industries (s) Pte Ltd - Woodlands (HQ)  
51 SENOKO ROAD  
Singapore 758133

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Apr 2023)	
Parts:	N/A	VOLVO FMX370 10.8 D 64R DAYCAB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD9160G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Bent	3,880.60 F	*3,880.60 FL
2	1		*SIDE STEP PANEL LH	Cracked	922.00 F	*922.00 FL
3	1		*SIDE STEP UPPER LH	Repair	566.00 F	*- FL
4	1		*SIDE STEP LOWER LH	Bent	568.50 F	*568.50 FL
5	1		*SIDE STEP COVER LH	Cracked	765.00 F	*765.00 FL
6	1		*SIDE STEP PANEL CAP LH	Cracked	360.20 F	*360.20 FL
7	1		*FRONT BUMPER LOWER ASSEMBLY	Bent / Distorted	1,880.60 F	*1,880.60 FL
8	1		*FRONT BUMPER VENT LH	Cracked	788.00 F	*788.00 FL
9	1		*FRONT BUMPER INNER BRACKET	Cracked	630.00 F	*630.00 FL
10	1		*FRONT HEADLIGHT HOUSING LH	Cracked	1,255.00 F	*1,255.00 FL
11	1		*FRONT SIDE BUMPER LOWER LH	Bent	1,095.00 F	*1,095.00 FL
12	1		*FRONT HEADLIGHT BRACKET LH	Cracked	1,150.00 F	*1,150.00 FL
13	1		*FRONT HEADLIGHT INNER BRACKET LH	Cracked	715.00 F	*715.00 FL
14	1		*SET FRONT HEADLIGHT LH	Serviceable	1,690.00 F	*- FL
15	1		*FOG LAMP BRACKET LH	Cracked	312.60 F	*312.60 FL
16	1		*FOG LAMP INNER BRACKET LH	Cracked	325.00 F	*325.00 FL
17	1		*FOG LAMP LH	Serviceable	520.00 F	*- FL
18	1		*FRONT FENDER LINER (BACK) LH	Serviceable	968.00 F	*- FL
19	1		*FRONT HEADLIGHT SIGNAL LAMP LH	Broken	315.00 F	*315.00 FL
20	1		*BODY STICKER	Necessary	350.00 FS	*80.00 FS
21	1		*SUNDRIES	Necessary	200.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,256.50	15,092.50
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	1,496.25
Total Parts (\$)	19,256.50	13,596.25

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE ,REINSTALL AND CHECK FRONT BUMPER WIRENES	New	350.00	200.00
2	LABOUR TO REMOVE ,REPAIR AND REINSTALL FRT BUMPER ,FRT DOOR L FRT PANEL INNER LH ,FRT BUMPER SUPPORT	New	5,000.00	2,560.00
3	LABOUR TO REMOVE AND REINSTALL BODY STICKER	New	1,920.00	0.00
4	LABOUR TO RESPRAY FRT DOOR LH ,FRT BUMPER ASSY	New	1,920.00	640.00
5	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	New	250.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,440.00</b>	<b>3,480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >