

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22009593/UVY3Q2
Date: 19/10/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNA00012982200	
Claimant Vehicle No : SMY6509A	Insured Vehicle No : GBA8565E	
Date of Loss: 26/09/2022	Nature of Claim: TP	Claim No: SNM22D206918/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMY6509A	
Make & Model: PEUGEOT 5008, 1.6 (A)	Engine No: 10JBHX3018137
Reg. Date: 05/04/2017 (Man. Year: 2016)	Chassis No: VF30EBHZTGS238356
Colour: Grey	Odometer: 187075 km
Engine Capacity: 1560 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17	Rear Tyre Size: 225/50 R17
Front Left Side: Firenza 6 mm	Rear Left Side: Firenza 6 mm
Front Right Side: Firenza 6 mm	Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,642.62	9,649.64	7,992.98	45.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,150.00	2,920.00	2,230.00	43.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	22,792.62	12,569.64	10,222.98	44.85
Approved Total (Overridden) (\$\$)		10,000.00		
(\$\$)	22,792.62	10,000.00	12,792.62	56.13
+ GST 7.00/7.00% (\$\$)	1,595.48	700.00	895.48	56.13
Nett Amount (\$\$)	24,388.10	10,700.00	13,688.10	56.13

INSPECTION

Date of Assignment: 30/09/2022	
Date Inspected: 29/09/2022 Inspected At:	Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE Singapore 417807
Estimated Period of Repair: 7.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Oct 2022)
Parts:	M1-MPV	PEUGEOT 5008 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMY6509A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	850.00 FL	*850.00 FL
2	1		*REAR BUMPER CENTER BRACKET	Not Necessary	120.00 FL	*- FL
3	1		*REAR BUMPER BRACKET	Not Necessary	98.80 FL	*- FL
4	1		*SET REAR BUMPER SIDE BRACKET	Bent	98.80 FL	*98.80 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	530.00 FL	*530.00 FL
6	1		*REAR BUMPER TOWING COVER	Not Necessary	80.00 FL	*- FL
7	1		*REAR END PANEL	Repair	480.50 FL	*- FL
8	1		*REAR END PANEL INNER FRAME	Not Necessary	360.00 FL	*- FL
9	1		*REAR REFLECTOR LH	Not Necessary	136.80 FL	*- FL
10	1		*REAR REFLECTOR RH	Broken	136.80 FL	*136.80 FL
11	1		*TAILGATE	Badly Dented	1,800.00 FL	*1,800.00 FL
12	2		*TAILGATE HINGE	Not Necessary	164.00 FL	*- FL
13	1		*TAILGATE GLASS	Not Necessary	680.00 FL	*- FL
14	1		*TAILGATE WEATHERSTRIP	Not Necessary	245.00 FL	*- FL
15	1		*TAILGATE EMBLEM 5008	Necessary	50.00 FL	*50.00 FL
16	1		*TAILGATE EMBLEM BLUE HDI	Necessary	50.00 FL	*50.00 FL
17	1		*TAILGATE LOGO	Not Necessary	150.00 FL	*- FL
18	1		*TAILGATE OUTER HANDLE	Cracked	160.00 FL	*160.00 FL
19	1		*TAILGATE LOCK	Twisted	550.00 FL	*305.00 FL
20	1		*TAILGATE BUFFER	Not Necessary	28.00 FL	*- FL
21	1		*TAILGATE FIX	No such part	160.80 FL	*- FL
22	1		*TAILLAMP LH	Cracked	600.00 FL	*600.00 FL
23	1		*TAILLAMP RH	Cracked	600.00 FL	*600.00 FL
24	1		*LOWER REAR PAN FIX	No such part	59.00 FL	*- FL
25	1		*LOWER TRIM	Not Necessary	447.00 FL	*- FL
26	1		*REAR WIPER	Not Necessary	107.00 FL	*- FL
27	1		*REAR WIPER MOTOR	Not Necessary	325.00 FL	*- FL
28	1		*REAR FENDER AIR VENT	Not Necessary	45.50 FL	*- FL
29	1		*FRONT ENGINE PROTECTOR	Not Necessary	325.00 FL	*- FL
30	1		*FRONT BUMPER	Torn	1,150.00 FL	*1,150.00 FL
31	2		*FRONT BUMPER RETAINER	Bent	274.00 FL	*274.00 FL
32	1		*FRONT SUPPORT PANEL	Cracked	625.00 FL	*625.00 FL
33	1		*FRONT BUMPER REINFORCEMENT	Bent	480.00 FL	*480.00 FL
34	1		*FRONT BUMPER LOGO	Not Necessary	150.00 FL	*- FL
35	1		*FRONT BONNET	Not Necessary	816.90 FL	*- FL
36	1		*FRONT BONNET LOCK	Not Necessary	320.90 FL	*- FL
37	1		*FRONT GRILLE	Cracked	285.00 FL	*285.00 FL
38	1		*FRONT LOWER GRILLE	Cut	220.00 FL	*220.00 FL
39	1		*FRONT FOG LAMP LH	Not Necessary	275.00 FL	*- FL
40	1		*FRONT FOG LAMP GARNISH RH	Cracked	275.00 FL	*165.00 FL
41	1		*FRONT FENDER LH	Not Necessary	715.50 FL	*- FL
42	1		*FRONT FENDER RH	Repair	715.50 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT FENDER INNERSHIELD LH	Not Necessary	186.50 FL	*- FL
44	1		*FRONT FENDER INNERSHIELD RH	Not Necessary	186.50 FL	*- FL
45	1		*HEADLAMP LH	Cracked	960.00 FL	*960.00 FL
46	1		*HEADLAMP RH	Cracked	960.00 FL	*960.00 FL
47	1		*HEADLAMP BRACKET LH	No such part	79.00 FL	*- FL
48	1		*HEADLAMP BRACKET RH	No such part	79.00 FL	*- FL
49	1		*FRONT NUMBER PLATE	Cracked	80.00 FS	*40.00 FS
50	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
51	1		*SET REAR REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
52	1		*REAR REVERSE CAMERA	Not Necessary	380.00 FS	*- FS
53	1		*REAR NUMBER PLATE	Scratched	80.00 FS	*40.00 FS
54	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
55	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
56	1		*WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
57	1		*JOINT SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,461.80	10,679.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,819.18	1,029.96
Total Parts (\$\$)	17,642.62	9,649.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ALL WIRING AND LIGHTING SYSTEM	New	200.00	30.00
2	REMOVE AND REFIT REAR WINDSCREEN	New	100.00	100.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	50.00
4	REMOVE AND REFIT ALL ACCIDENT DAMAGED AREAS	New	300.00	0.00
5	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	2,200.00	1,200.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	2,000.00	1,500.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	40.00
Gross Labour Cost (S\$)			5,150.00	2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >