

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/GRB22002896/GQY3E2-1**Date:** 17/10/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01

**Claimant Vehicle No :** SMX4056H **Insured Vehicle No :** SMV9278L

Date of Loss: 19/03/2022 Nature of Claim: TP Claim No: MFL2022D0001343

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX4056H**

Make & Model: MERCEDES-BENZ A200, 1.6 FL STYLE (R17 HLG) (A) Engine No: 27091031060200

Reg. Date: 16/02/2017 (Man. Year: 2016) Chassis No: WDD1760432J507561

Colour: White Odometer: 71580 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40Z R18 Rear Tyre Size: 225/40Z R18

Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,903.71	3,112.82	790.89	20.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,523.50	1,040.00	483.50	31.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,427.21</b>	<b>4,152.82</b>	<b>1,274.39</b>	<b>23.48</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,427.21</b>	<b>3,300.00</b>	<b>2,127.21</b>	<b>39.20</b>

INSPECTION

Date of Assignment: 26/08/2022

Date Inspected: 04/04/2022 Inspected At:

S.A Infinte PaintWorks Pte Ltd (HQ)  
25 Kaki Bukit Road 4, #06-43, Synergy @ KB  
Singapore 417800

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference	
Part Source:	MRM-SG    Version: 1.0 (Last Synchronised: 17 Oct 2022)
Parts:	144    MERCEDES-BENZ A200 1.6 FL STYLE (R17 HLG) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's    (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMX4056H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE EMBLEM A200	Necessary	65.00 FL	*65.00 FL
2	1		*TAIL GATE EMBLEM LOGO	Necessary	85.00 FL	*85.00 FL
3	1		*TAIL GATE EMBLEM C&C	Necessary	45.00 FL	*45.00 FL
4	1		*REAR BUMPER	Deformed	1,638.00 FL	*1,421.50 FL
5	1		*REAR BUMPER CENTER BRACKET	Deformed	105.00 FL	*105.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Bent	655.00 FL	*565.66 FL
7	1		*REAR BUMPER LOWER LID	Deformed / Torn	438.30 FL	*356.00 FL
8	1		*REAR BUMPER LIP INNER BRACKET	Fractured / Deformed	109.00 FL	*109.00 FL
9	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Malfunction(2Pcs Only)	936.80 FL	*468.40 FL
10	1		*REAR END PANEL TOP GARNISH	Holder Broken	204.80 FL	*204.80 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
12	1		*TAIL GATE (NPA)	Repair	0.00 FL	*- FL
13	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
					Sub Total (\$\$)	4,331.90    3,455.36
					- List Item Discount on L Items 10.00/10.00% (\$\$)	428.19    342.54
					Total Parts (\$\$)	3,903.71    3,112.82

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	540.00	400.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	700.00	600.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	30.00	0.00
4	REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR & CONDUCT DISTANCE SAFETY SETTING	New	76.50	40.00
5	SPECIALIST CHARGES - DIAGNOSTIC FAULT CODE / RESET	New	150.00	0.00
6	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / READJUST ON ANGLE OF LIGHT INTENSITY)	New	27.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,523.50</b>	<b>1,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >