

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22009597/AVY3Q2**Date:** 08/11/2022**REFERENCE**

Insured/Claimant: Lee Teck Soon Eric Policy No: SP2002159546-01
Date of Loss: 23/09/2022 Nature of Claim: OD Claim No: 202222007006SL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNE818R**
Make & Model: BMW 740LI, 3.0 (A) Engine No: 23329419B58B30A
Reg. Date: 01/03/2016 (Man. Year: 2015) Chassis No: WBA7E22090G522977
Colour: White Odometer: 105375 km
Engine Capacity: 2998 cc
Market Value/New Car Price: S\$158,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35 R21 Rear Tyre Size: 245/35 R21
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,032.60	4,559.50	20,473.10	81.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	480.00	570.00	54.29
Paintwork Labour	800.00	500.00	300.00	37.50
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,882.60	5,539.50	21,343.10	79.39
- Excess (S\$)	0.00	800.00	-800.00	
(S\$)	26,882.60	4,739.50	22,143.10	82.37
+ GST 7.00/7.00% (S\$)	1,881.79	331.77	1,550.02	82.37
Nett Amount (S\$)	28,764.39	5,071.27	23,693.12	82.37

INSPECTION

Date of Assignment: 29/09/2022 Present Location: Success United Pte Ltd (HQ)
Date Inspected: 30/09/2022 Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub
Singapore 417921
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2022)
Parts: 143	BMW 740LI 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SNE818R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front Bonnet	Repair	3,500.00 F	*- F
2	1		*Front Bumper Assy	Deformed	2,100.00 F	*2,100.00 F
3	1		*Front Bumper Inner Base Frame	Not Necessary	320.00 F	*- F
4	2		*Front Bumper Side Holder (LH/RH)	Not Necessary	180.00 F	*- F
5	2		*Front Bumper Bracket (LH/RH)	Not Necessary	130.00 F	*- F
6	1		*Front Bumper Inner Sponge	Deformed	110.00 F	*110.00 F
7	1		*Front Bumper No.Plate Garnish	Deformed	90.00 F	*90.00 F
8	1		*Front PDC Sensor (Packing Distance Sensor)	Not Necessary	395.00 F	*- F
9	1		*Front Bumper Lower Air Grille (Center)	Cracked	150.00 F	*150.00 F
10	1		*Front Bumper Inner Lower Bracket	Not Necessary	450.00 F	*- F
11	2		*Front Grille Assy (LH/RH)	Cracked	460.00 F	*460.00 F
12	1		*Front Bumper Reinforcement	Not Necessary	850.00 F	*- F
13	2		*Front Headlamp Assy (LH/RH)	Not Necessary	11,940.00 F	*- F
14	2		*Front Headlamp Bracket (LH/RH)	Not Necessary	156.00 F	*- F
15	1		*Front Grille Inner Motor	Not Necessary	220.00 F	*- F
16	1		*Front Grille Inner Vent	Not Necessary	430.00 F	*- F
17	1		*Front Bumper Clips	Necessary	30.00 FS	*30.00 FS
18	1		*Front No.Plate with Frame	Repeated	45.00 FS	*- FS
Supplementary #1						
19	1		*BUTTERFLY COATING		588.00 FS	*588.00 FS
Supplementary #2						
20	1		*FRONT NO. PLATE WITH FRAME (AMENDED PRICE)	Cracked	130.00 FS	*130.00 FS
Supplementary #3						
21	1		*Front Upper Air Flaps	Cracked	420.00 F	*420.00 F
22	1		*Front Lower Air Flaps	Cracked	135.00 F	*135.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$)	22,829.00	4,213.00
+ Margin on L,N Items 10.00/10.00% (\$)	2,203.60	346.50
Total Parts (\$)	25,032.60	4,559.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	To putty & respray painting on bonnet, bumper, support panel	New	800.00	500.00
<u>Labour Items</u>				
2	To remove, repair & replaced damaged body parts, realign bodywork, &where consistent to the accident	New	900.00	450.00
3	To remove, rearrange electrical wirings, check lightings	New	150.00	30.00
			Gross Labour Cost (\$)	1,850.00
				980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >