

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2022)
Parts: 143 BMW 740LI 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Success United Pte Ltd/SNE818R/28/09/2022 17:48
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Bonnet <i>Del'd</i>	0.00	0.00	*3,500.00 F ✓
2	1		*Front Bumper Assy <i>Del'd</i>	0.00	0.00	*2,100.00 F ✓
3	1		*Front Bumper Inner Base Frame	0.00	0.00	*320.00 F ?
4	2		*Front Bumper Side Holder (LH/RH) <i>Me n</i>	0.00	0.00	*180.00 F ✓
5	2		*Front Bumper Bracket (LH/RH)	0.00	0.00	*130.00 F ?
6	1		*Front Bumper Inner Sponge <i>2? CAS</i>	0.00	0.00	*110.00 F ?
7	1		*Front Bumper No.Plates Garnish <i>Del'd</i>	0.00	0.00	*90.00 F ✓
8	1		*Front PDC Sensor (Packing Distance Sensor) <i>?</i>	0.00	0.00	*395.00 F ?
9	1		*Front Bumper Lower Air Grille (Center) <i>Del'd</i>	0.00	0.00	*150.00 F ✓
10	1		*Front Bumper Inner Lower Bracket <i>?</i>	0.00	0.00	*450.00 F ?
11	2		*Front Grille Assy (LH/RH) <i>Del'd</i>	0.00	0.00	*460.00 F ✓
12	1		*Front Bumper Reinforcement <i>BT</i>	0.00	0.00	*850.00 F ?
13	2		*Front Headlamp Assy (LH/RH)	0.00	0.00	*11,940.00 F ?
14	2		*Front Headlamp Bracket (LH/RH) <i>Me n</i>	0.00	0.00	*156.00 F ✓
15	1		*Front Grille Inner Motor <i>?</i>	0.00	0.00	*220.00 F ?
16	1		*Front Grille Inner Vent <i>?</i>	0.00	0.00	*430.00 F ?
17	1		*Front Bumper Clips <i>m</i>	0	0.00	*30.00 FS ✓
18	1		*Front No.Plates with Frame <i>Del'd</i>	0	0.00	*45.00 FS ✓

F=Franchise part. S=SpcNett.

Sub Total (S\$)	21,556.00
+ Margin on L,N Items 10.00% (S\$)	2,148.10
Total Parts (S\$)	23,704.10

Success United Pte Ltd/SNE818R/28/09/2022 17:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Gmo
18/10

Estimates on Miscellaneous Items

are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	To putty & respray painting on bonnet, bumper, support panel	New	800.00 500
<u>Labour Items</u>			
2	To remove, repair & replaced damaged body parts, realign bodywork, &where consistent to the accident	New	900.00 450
3	To remove, rearrange electrical wirings, check lightings	New	150.00 30
Gross Labour Cost (\$\$)			1,850.00

Success United Pte Ltd/SNE818R/28/09/2022 17:48. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian Lj
30/09/22
04 Days
P/P.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2022)
Parts: 143	BMW 740LI 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: Success United Pte Ltd/SNE818R/18/10/2022 10:16	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Upper Air Flaps 	0.00	0.00	*420.00 F
2	1		*Front Lower Air Flaps 	0.00	0.00	*135.00 F
Sub Total (S\$)						555.00
+ Margin on L,N Items 10.00% (S\$)						55.50
Total Parts (S\$)						610.50

F=Franchise part.

Success United Pte Ltd/SNE818R/18/10/2022 10:16. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**