

ASS. REC. BY:

REF:

C72 / 22009601/Kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKH 9336A

Yr Regn:

01, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. SIK 200

c.c

1796

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

181159

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 172 448215 025142

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: M16

225/40ZR18

R: Tourador

255/35ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / M7 / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

29/9/22

D.O.I.

30/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

10/11 11:00 @ 4600t 4850t Car

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fines

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

ARC

Automotive Repair Centre Pte Ltd

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2209-530

DATE : 29-Sep-2022

POLICY NO. :

VEHICLE REG. NO. : SKH9336A

VEHICLE MAKE : MERCEDES BENZ / SLK 200 A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>1519.20</i>	<i>Buc/ma</i> 1	\$ 2,820.00	\$ 2,820.00 ✓
2	Rear Bumper Retainer RH	1	\$ <i>50</i> 50.00	\$ 50.00 X
3	Rear Bumper Retainer LH	1	\$ <i>50</i> 50.00	\$ 50.00 X
4	Rear Bumper Lower	1	\$ <i>248</i> 248.00	\$ 248.00 ✓
5	Rear Bumper Tow Cover	1	\$ <i>80</i> 80.00	\$ 80.00 X
6	Rear Reinforcement	1	\$ 700.00	\$ <i>700</i> 700.00 X
7	Rear Sponge	1	\$ 210.00	\$ <i>210</i> 210.00 ✓
8	Bootlid <i>2160</i>	<i>Bz</i> 1	\$ 2,866.00	\$ 2,866.00 ✓
9	Bootlid SLK200 Emblem	<i>me</i> 1	\$ 120.00	\$ 120.00 ✓
10	Bootlid Mercedes Emblem	<i>me</i> 1	\$ 120.00	\$ 120.00 ✓
11	Rear Boot Weatherseal Rubber	<i>pu</i> 1	\$ 250.00	\$ 250.00 X
12	End Panel Garnish	<i>pu</i> 1	\$ 196.00	\$ 196.00 X
13	Tail Lamp RH	<i>ca</i> 1	\$ 800.00	\$ 800.00 ✓
Total Spare Parts				\$ 8,510.00
SPECIAL NETT				
14	Reverse Sensors	1	\$ 280.00	\$ <i>280</i> 280.00 X
15	Rear Bumper Clips	<i>me</i> 10	\$ 5.00	\$ 50.00 ✓
Total Special Nett				\$ 50.00
LABOUR				
16	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 750.00	\$ 750.00 <i>500</i>
17	Spray Paint (Rear Bumper, Bootlid, Rear Reinforcement and End Panel)	1	\$ 1,000.00	\$ 1,000.00 <i>500</i>
18	Diagnose, Rectify, Calibrate Fault Codes	1	\$ 200.00	\$ <i>200</i> 200.00 X
19	Remove and Replace Reverse Sensors	1	\$ 100.00	\$ 100.00 <i>60</i>
20	Remove, Align and Refit Rear Exhaust	1	\$ 80.00	\$ <i>80</i> 80.00 X
21	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00 <i>20</i>
Total Labour				\$ 2,160.00
Amount Before Excess				\$ 10,720.00
Add GST @ 7%				750.40
Total Amount Payable				\$ 11,470.40

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.