

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III22007642/ECY3E2-1
Date: 18/11/2022

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0005826_01
Claimant Vehicle No :	SMQ1774A	Insured Vehicle No :	SMW4471Y
Date of Loss:	04/08/2022	Nature of Claim:	TP
		Claim No:	MFL2022D0004319

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ1774A		
Make & Model:	HONDA JADE 1.5 RS CVT, 1.5 (A)	Engine No:	L15B3250323
Reg. Date:	19/07/2017 (Man. Year: 2016)	Chassis No:	JHMF5860FC200321
Colour:	Blue	Odometer:	59265 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	225/45Z R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,879.28	2,205.36	1,673.92	43.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,000.00	1,520.00	60.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,399.28	3,205.36	3,193.92	49.91
Approved Total (Overridden) (\$\$)		2,550.00		
(\$\$)	6,399.28	2,550.00	3,849.28	60.15
+ GST 7.00/7.00% (\$\$)	447.95	178.50	269.45	60.15
Nett Amount (\$\$)	6,847.23	2,728.50	4,118.73	60.15

INSPECTION

Date of Assignment:	28/09/2022	
Date Inspected:	11/08/2022	Inspected At: V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center Singapore 627605
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Nov 2022)	
Parts:	N/A	HONDA JADE 1.5 RS CVT 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ1774A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	980.70 FL	*980.70 FL
2	2		*REAR TAILGATE HINGES L/R	Not Necessary	82.00 FL	*- FL
3	1		*REAR TAILGATE OUTER CHROME GARNISH	Cut	220.00 FL	*220.00 FL
4	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	168.70 FL	*- FL
5	1		*REAR TAILGATE MECHANISM LOCK	Bent	88.90 FL	*88.90 FL
6	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	92.30 FL	*- FL
7	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	27.50 FL	*- FL
8	1		*REAR BUMPER	Cracked	782.30 FL	*782.30 FL
9	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Not Working(2Pcs Only)	670.00 FL	*335.00 FL
10	2		*REAR BUMPER SIDE RETAINER L/R	Bent	46.00 FL	*46.00 FL
11	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	282.20 FL	*- FL
12	1		*REAR BUMPER CENTER GARNISH	Cracked	139.80 FL	*139.80 FL
13	1		*REAR END PANEL INNER TOP GARNISH	Repair	155.50 FL	*- FL
14	6		*REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	39.00 FL	*39.00 FL
15	1		*REAR END PANEL	Repair	539.10 FL	*- FL
16	1		*REAR END PANEL BOOTLID ANTENNA SENSOR	Not Necessary	165.10 FL	*- FL
17	1		*REAR END PANEL BOOTLID ANTENNA SENSOR BUZZER	Not Necessary	95.00 FL	*- FL
18	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
19	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*40.00 FS
20	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,794.10	2,731.70
- List Item Discount on L Items 20.00/20.00% (\$)	914.82	526.34
Total Parts (\$)	3,879.28	2,205.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTNG HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	120.00	30.00
2	TO REMOVE, REINSTALL TOP TRIM, TRIM GARNISH, TRIM LINER	New	100.00	30.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	400.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	40.00
5	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	500.00
Gross Labour Cost (\$\$)			2,520.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >