



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 2081A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	698.00	-
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	SERVICEABLE	58.30	-
1	TAILAMP LH (CONSISTENT)	SERVICEABLE	524.00	-
1	REAR FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	875.00	-
1	REAR FENDER COWLING LH (CONSISTENT)	SERVICEABLE	318.00	-
	LESS 20% DISCOUNT		-494.66	-
			1,978.64	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	250.00	-
			330.00	-
<b><u>LABOUR</u></b>				
	SPRAY PAINTING ON AFFECTED AREAS .		500.00	400.00
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDER LH .		500.00	200.00
	TO CHECK ELECTRICAL WIRING.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT REVERSE SENSOR .	NOT NECESSARY	150.00	-
	REMOVE AND REFIX REAR UPHOLSTERY .	NOT NECESSARY	400.00	-
	APPLY ANTI RUST ON AFFECTED AREAS .	NOT NECESSARY	120.00	-
			1,750.00	600.00
<b>GRAND TOTAL</b>			<b>4,058.64</b>	<b>600.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>600.00</b>

Report Ref No. CC4/ASM22009603/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.