

ASS. REC. BY:

REF:

ASM/22009603/ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of 05-21

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$84k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.61 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMN 2081A

Yr Regn: 07, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda

c.c. 1496

Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 220310

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

GP5 - 1342785

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R/Bal. 9 mm

R/Bal. 9 mm

L/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 27/6/22

D.O.A. 29/9/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/10 0600L Cahr

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S - RS, SI

Fees

Others

Add Fee: ☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737986

HP: 98888885

Estimation

Date: 30/9/2022

Vehicle: SMN2081A

Make / Model: HONDA FIT

Chassis No: AXA

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER	1	\$ 698.00	\$ 698.00
2	REAR BUMPER SIDE RETAINER LH	1	\$ 58.30	\$ 58.30
3	TAILAMP LH	1	\$ 524.00	\$ 524.00
4	REAR FENDER LH	1	\$ 875.00	\$ 875.00
5	REAR FENDER COWLING LH	1	\$ 159.00	\$ 318.00
				\$ 2,473.30
			Less 20%	\$ 494.66
			Total	\$ 1,978.64
S/Nett items:				
1	REAR BUMPER CLIP SET	1	\$ 80.00	\$ 80.00
2	REVERSE SENSOR SET	1	\$ 250.00	\$ 250.00
				\$ 2,070.00
Labour to:				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 500.00	\$ 500.00
3	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
4	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
5	REMOVE AND REFIX REAR UPHOLSTERY	1	\$ 400.00	\$ 400.00
6	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 120.00	\$ 120.00
				\$ 6,440.00
Parts Replacement Amount				\$ 4,048.64
Total Amount for Labour				\$ 6,440.00
Total Amount				\$ 10,488.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
Showing After Paint
3 days
8600h